

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65378

Completed : 30 NOV 21 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10606 Description : 2021 TT COACHMEN APEX NANO 208BHS
Tag : Date In : 01 OCT 21 Mileage : 0
Author : BH Promised : 31 OCT 21
Location : 1129 AP SET Date Sched :
Serial# : 5ZT2CXKB4ML009715 Chassis# : 5ZT2CXKB4ML009715
Warr. Date : 11 SEP 20 Cust PO# :
Print Date : 09 DEC 21

Job # Description JOB INFORMATION Type Bill To

6 CUSTOMER STATES THAT THE FRONT WINDOW (ABOVE LP W 10024 FORES
TANKS) IS LEAKING AND WATER IS GETTING INSIDE THE
UNIT.

Job # Part No Description PARTS Bill to Qty Price Total

6 6354 DECAL #35A NANO LO W-10024 1 1.86 1.86
6 6355 FRONT CAP WINDOW W-10024 1 271.96 271.96

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

6 Z990 MISC LABOUR CODE (EXTE SAR W-10024 0.00 130.00 0.00
6 Z990 MISC LABOUR CODE (EXTE SAR W-10024 0.00 130.00 0.00
6 Z990 MISC LABOUR CODE (EXTE SAR W-10024 0.00 130.00 0.00
6 Z990 MISC LABOUR CODE (EXTE W-10024 0.00 130.00 0.00

Job # Sublet Description SUBLET bill to Vendor Total

6 SEIMERS W-10024 317-SIEMERS GL 250.00

Job # Excode Description EXTRAS bill to Qty Price Total

6 FRT UPS-DECAL W-10024 1.00 15.53 15.53
6 FRT FREIGHT & CRATE - WINDOW W-10024 1.00 280.00 280.00

CUSTOMER COMMENTS

CHRIS TO TAKE UNIT DOWN THURSDAY FOR WINDOW INSTALL
APPROVED

Continued on page 2

Work Order : 65378

BH SENT IN PREAUTH FOR WINDOW 11-29
 APT SET 1129
 SEE RO 65387
 UNIT NOT HERE

HAS ANOTHER RO CHECK PARTS
 SIEMERS TO INSTALL GLASS
 FRONT WINDOW ARRIVED IN SHOP 1A 10-15-21...CAM
 DECAL ARRIVED 10-11-21
 CUSTOMER HAS CAMPER
 STILL NEED TO PUT PREAUTH IN
 WAITING TO GET A EST FROM SEIMERS SO I CAN TURN IT IN TO FOREST
 RIVER
 ORDERED WINDSHIELD AND NANO DECAL PER BEN. 10-1-21
 BH AND GARY TALKED AND THEY ARE OK FOR ME TO ORDER A WINDOW
 AND HAVE IT SUBLET OUT TO FIX IT 10-01
 GARY SAID CALL SOME ONE LOCAL AND HAVE THEM REPLACE THE WINDOW
 SEIMERS SAID YOU HAVE A BETTER CHANCE OF BRAKING THE WINDOW THEN
 FIXING
 CALLED SEIMERS AND TEXTED A PIC WAITING FOR THEM TO TEXT BACK
 SAFELITE SAYS I HAVE TO TAKE IT TO LOIVILLE THATS NOT HAPPENING
 RO FOR SAFELITE 585018
 GARY FROM FOREST RIVER SAID TO GET SAFELITE OUT TO FIX IT. 10-01
 IT IS JUST LIKE A CAR WINDSHEILD

 BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	10024	273.82	0.00	250.00	295.53	0.00	819.35
	Totals	273.82	0.00	250.00	295.53	0.00	819.35
