



RECREATIONAL VEHICLES

Claim CLAIM1642 (KZ0002788)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	Repair VIN	Pre- auth Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Date of Purchase
CLAIM1642 (KZ0002788)	26973	4/10/2026	4/30/2026	4EZTK1318T5032217	CUST-002602	TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	5/9/2026 Pre-delivery

Deny code	Item number	Name	Sub Qty	Appr Qty	Qty Returned	Dealer price	Markup	Sub total	Appr total	Sub Freight	Appr Freight	Sublet	Status
	SHOP	SHOP SUPPLIES	1	1	0	0.00	0.00	0.00	2.00	0.00	0.00	0.00	Approved
	162295	CURTAIN,SHOWER,72X72,WHITE,12 HOLES	1	1	0	0.00	0.00	0.00	15.28	0.00	0.00	0.00	Approved

Component Model 1	Component Serial Number 1	Sub Qty	Appr Qty	Qty	Dealer price	Markup	Sub total	Appr total	Sub Freight	Appr Freight	Sublet	Status
FC_Parts	Freight Charge Parts	1	1	0	0.00	0.00	0.00	0.00	22.50	22.50	0.00	Approved
SHOP	SHOP SUPPLIES	1	1	0	0.00	0.00	0.00	2.00	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
5540_02_A	Repair, General, Putty, Clean, Sand, Etc. - Delam/Peeling/Flaking - Repair/adjust/tighten		0.2	0.1	17.5	0	1	0.1	Approved

Complaint Bathroom door is chipped in two places
Cause Noted on DAF
Correction Fill, color, and blend area to color match

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
6604_01_B	R/R Shower Curtain - Damaged - Replace		0.2	0.1	17.5	0	1	0.1	Approved

Complaint Shower curtain is stained and makes it look used
Cause Noted on DAF
Correction Remove and replace the shower curtain with new one

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
6623_01_A	R/R Bedspread - Damaged - Repair/adjust/tighten		0.5	0.2	35	0	1	0.1	Approved

Complaint Bed sheet is full of OD saw dust and wood chips
Cause Noted on DAF, this was done at the factory, this is too much to just brush of the sheet
Correction Remove sheet, clean all the wood chips off bed and surrounding area, wash and dry sheet



RECREATIONAL VEHICLES

Claim CLAIM1642 (KZ0002788)

Last Modified By

Submitted parts & subLet	0.00	Approved parts & subLet	19.28
Submitted labor & subLet	157.50	Approved labor & subLet	70.00
Submitted freight	22.50	Approved freight	22.50
Total Submitted	<u>180.00</u>	Total approved	<u>111.78</u>