

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65482

Completed : 31 JAN 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10842 Description : 2021 TT FOREST RIVER CHEROKEE GREY
Tag : Date In : 13 OCT 21 Mileage : 0
Author : BJW Promised : 29 JAN 22
Location : 0131 SEE IF BH CAN Date Sched :
Serial# : 4X4TCKY22NK078646 Chassis# : 4X4TCKY22NK078646
Warr. Date : Cust PO# :
Print Date : 31 JAN 22

Job #	Description	JOB INFORMATION	Type	Bill To
-------	-------------	-----------------	------	---------

1	COMPLAINT: BAGGAGE DOOR IS SCRATCHED		W	10024 FORES
	CORRECTION: PULLED CAMPER IN SLOW WITH SNOW AND ICE ALL AROUND. REMOVED THE OLD DOOR FROM UNIT AND TEST FIT THE NEW DOOR. THE DOOR WAS NOT AS TALL AS THE OPENING. I HAD TO SHIM THE LOWER PART OF THE DOOR TO GET IT TO BE HIGH ENOUGH TO SEAL AT THE TO OF THE DOOR FRAME. INSTALLED NEW DOOR AND CHECKED TO SEE IF THE DOOR AND DOOR FRAME FIT GOOD. I SEEN THAT THE SEAL AT THE UPPER PART OF THE DOOR DID NOT MAKE FULL CONTACT WITH THE SEAL. I TRIED THE TAKE PICTURES OF THE GAP. BUT THE DID NOT COME OUT VERY GOOD. I ADJUSTED THE LATCH ON THE DOOR TO TRY TO GET IT TO SEAL BETTER. I DOES LOOK BETTER. I THEM SEALED ALL THE WAY AROUND THE DOOR FRAME.			

2	COMPLAINT: THE SEAL ON THE OUTSIDE KITCHEN COMPARTMENT DOOR IS WARPED AND WAVY.		W	10024 FORES
	CORRECTION: REMOVED OLD SEAL AND CLEANED OFF THE ADHESIVE. INSTALLED NEW SEAL ON DOOR FRAME.			

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
1	20X70341A	DOOR, COMPARTMENT		W-10024	1	181.80	181.80
2	311450	Seal - D Seal - EP		W-10024	100	0.31	31.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
1	Z990	MISC LABOUR CODE (EXTE SAR			W-10024	0.00	130.00	0.00

Continued on page 2

Work Order : 65482

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   1  Z990      MISC LABOUR CODE (EXTE GAH  W-10024    0.50    130.00    65.00
   2  Z990      MISC LABOUR CODE (EXTE GAH  W-10024    0.40    150.00    60.00

```

```

*****
Job #  Excode    Description  EXTRAS          bill to    Qty    Price    Total
*****
   1  FRT        UPS-COMP DOOR                W-10024    1.00    36.66    36.66
   2  FRT        UPS-SEAL                    W-10024    1.00    15.69    15.69

```

CUSTOMER COMMENTS

SEAL IN BACKROOM 1-19-22...CAM
NEED TO SENT IN DAF FORM WHEN WE SENT IN FOR CLAIM
BH GOT APPROVEL
BH SENT IN FOR PREAUTH
COMP DOOR ARRIVED IN BACKROOM 1-6-22...CAM

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	10024	212.80	125.00	0.00	52.35	0.00	390.15
	Totals	212.80	125.00	0.00	52.35	0.00	390.15