



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 27212



WO #: 27212

Customer: 49109 - HILL, PAUL
 Address: 1444 WINDFIELD DRIVE
 MORRISTOWN, TN
 37813

Home Phone: (423) 748-4521

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11320
 Stock Desc: 2026 TT FOREST RIVER
 ROCKWOOD MINI 2523MBR
 Model: 2523MBR
 Serial #: 4X4TRLB28TZ202372
 Chassis #:
 Mileage:
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date: 28 MAY 26
 Date In: 27 MAY 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 01 JUN 26
 Warr. Date: 28 MAY 26

Job #1 - Warranty

COMPLAINT: THERE IS A NIC IN THE WALL TRIM GOING INTO THE BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
 LABOR .20

Labor

Job #	Description	Hours	Total
1	REPAIRED AREA	0.10	17.50

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	5.99	5.99

Subtotal for Job #1: 23.49

Job #2 - Warranty

COMPLAINT: SEVERAL NAIL HOLES NOT FILLED IN ON THE LIVING ROOM SLIDE. THIS IS ON BOTH SIDES AND ACROSS THE TOP.

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREAS
 LABOR .30

Labor

Job #	Description	Hours	Total
2	REPAIRED AREA	0.30	52.50

Subtotal for Job #2: 52.50

Job #3 - Warranty

COMPLAINT: SMALL PUNCTURE IN PANTRY DOOR, KITCHEN AREA

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
 LABOR .10

Customer #: 49109
 HILL, PAUL



Labor			
Job #	Description	Hours	Total
3	REPAIRED AREA	0.30	52.50
Subtotal for Job #3:			52.50

Job #4 - Warranty

COMPLAINT: CRACK ON THE TOP OF THE CABINET DOOR IN THE BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor			
Job #	Description	Hours	Total
4	REPAIRED AREA	0.30	52.50
Subtotal for Job #4:			52.50

Parts Total:	0.00
Labour Total:	175.00
Sublet Total:	0.00
Extras Total:	5.99
WORK ORDER TOTAL:	180.99

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 01 Jun 2026

Customer Signature : _____



Customer #: 49109
HILL, PAUL

