



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73419
 Promised Date:
 20 MAY 26



WO #: 73419

Customer Name: 55266 - MILKS,
 CHARLES HARLAND JR

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 2024 VENTANA 4369
 Serial#: 416351
 Chassis#: 4UZFCHFE4PCUS0691
 Miles/Hrs: 3621
 Tag#: 7168
 Purchased Date:
 Warranty Date:

Date In: 27 MAY 26
 Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES VALVE TO FILL FRESH WATER TANK LEAKING WHILE USING IN WET BAY COMPARTMENT

CAUSE: Water hose lines, and water lines leaking

CORRECTION: Freshwater tank fill is leaking from the elbows and waterlines when adding supply water to the system. The whole front water system panel has to be unscrewed and taken off in order to get to the lines that need repairing. Other lines have to be disconnected and unscrewed. Then reinstalled to factory specs. Water softener hoses and container needs to be disconnected, then reinstalled once new parts have been installed. Outside shower and sewage rinse has to be removed. Once everything is installed correctly and completed all water lines need to be reinstalled and tested for leaks.

New elbows , water lines, pex clamps needed and off and on water switch need to be ordered.

Photos attached
 Request 4.5HRS

Labor

Job #	Description	Total
1	WATER SYSTEM TROUBLESHOOT	N/C
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES DAY SHADE WILL NOT GO ALL THE WAY UP AT PASSENGER SEAT

CAUSE: Unknown

CORRECTION: Both black out shade a day shade do not roll up all of the way up to the proper place ie factory place. They only roll up half way. The wood vance needs to be unscrewed and taken off in order to get to the shades. The day shade needs to be unscrewed first and replaced with new shade. The black out shade needs to be unscrewed and replaced. New install the black out shade needs to be placed into factory location first and then the day shade. They need to be tested and adjusted.

Day shade width 18x45
 Black out shade 18x47
 Photos attached
 Request 1.00HRS

Labor

Job #	Description	Total
2	WINDOW SHADE DIAGNOSE	N/C

Customer #: 55266
 MILKS, CHARLES
 HARLAND JR



W/O: 73419
Promised Date: 29 MAY 26

Subtotal for Job #2: 0.00

Job #3 - Warranty
LEAVE BATTERIES ON

Subtotal for Job #3: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 27 May 2026

Customer Signature : _____



Customer #: 55266
MILKS, CHARLES
HARLAND JR

