

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65566

Completed : 29 NOV 21 Customer : 1013 - KEYSTONE RV CO -
Licence # : Invoice # :
Stock No : 10722 Description : 2021 5W KEYSTONE SPRINGDALE 340FWBH
Tag : Date In : 25 OCT 21 Mileage : 0
Author : BH Promised :
Location : 1200 CHECK WORK Date Sched :
Serial# : 4YDF3402XM3110422 Chassis# : 4YDF3402XM3110422
Warr. Date : 19 JUN 21 Cust PO# :
Print Date : 29 NOV 21

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT:	LEAKING NEAR THE REAR OF THE CAMPER UNDER THE RESTROOM AREA CUSTOMER FILLED THE FRESH TANK AND AFTER HE WAS DONE 5 MIN AFTER IT STARTED TO LEAK AND THEN WHEN HE GOT TO THE CAMPGROUND IT LEAKED ALSO...WATER PUMP WAS NOT LOOSEING PRESSURE LEAKED FOR 10 TO 15 MIS WHILE CUSTOMER WAS LOADING THE CAMPER WHEN AT THE CAMP SITE AFTER ABOUT 2-3 HRS IT STARTED TO LEAK AGAIN. IT WAS NOT FILLED WHILE AT THE CAMP SITE. THIS IS THE FIRST TIME CUSTOMER HAS FILLED THE FRESH TANK AND IT LEAKED. HE HAS FILLED THE FRESH TANK BEFORE AND THIS DIDNT HAPPEN.	W	1013 KEYST

CAUSE: CHECK FOR LEAKS ON FRESH TANK. CUT OPEN UNDERBELLY TO LOOK AT TANK FITTINGS. WHEN FILLING THE TANK I NOTICED THE DRAIN FITTING IS CRACKED. THIS IS A "SUN" WELDED FITTING. NEED TO REPLACE THE TANK. PICS ON ONEDRIVE.

CORRECTION: cut open underbelly. removed water lines and diode pack from tank. loosened brackets that hold the tank in place. removed support "bands" from main support. pulled tank. removed fittings from old tank and installed on new tank. removed diode pack and insstalled on new tank. installed new drain line and valve on new tank. installed new tank. secured support " bands" under tank. positioned support beams in place and secured with tech screws. wired up diode pack. secured water lines to new tank. filled

Work Order : 65566

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****

```

tank to test for leaks and test tank
level indicator. taped up underbelly.

```

*****
Job # Part No Description                PARTS                Bill to   Qty   Price   Total
*****
1     437088  FRESH WATER TANK                W-1013    1    129.72  129.72
1     30803    30803 1/2" MALE EL                    W-1013    1     2.31   2.31
1     5677     1/2" MTP X 1/2" PE                W-1013    1     1.37   1.37
1     30879    30879 Shut Off Valve; PEXLock W-1013    1     6.14   6.14

```

```

*****
Job#  Lab Code  Description                LABOUR  Mech Bill to   Hrs   Rate   Total
*****
1  Z990      MISC LABOUR CODE (EXTE  W-1013    0.00  130.00  0.00
1  Z990      MISC LABOUR CODE (EXTE ZMS W-1013    0.43  130.00  55.90
1  Z990      MISC LABOUR CODE (EXTE ZMS W-1013    0.43  130.00  55.90
1  Z990      MISC LABOUR CODE (EXTE ZMS W-1013    0.14  130.00  18.20
1  Z990      MISC LABOUR CODE (EXTE ZMS W-1013    1.00  130.00  130.00
1  Z990      MISC LABOUR CODE (EXTE ZMS W-1013    1.00  130.00  130.00

```

```

*****
Job #  Excode   Description                EXTRAS                bill to   Qty   Price   Total
*****
1     SS        SHOP SUPPLIES                W-1013    1.00   0.00   0.00
1     FRT       FREIGHT                        W-1013    1.00  72.45  72.45

```

CUSTOMER COMMENTS

TANK ARRIVED 11-8-21 IN WHITE TRAILER.
ORDERED TANK PER BEN. 11-2-21
BH GOT APPROVEL 11-02
BH SENT IN PREAUTH WAINTING TO HEAR BACK 10-27

BILLINGS SUMMARY

```

Type Bill Id      Parts   Labour   Sublet   Extras   Tax   Total
*****
W    1013          139.54  390.00   0.00    72.45  0.00  601.99
Totals          139.54  390.00   0.00    72.45  0.00  601.99

```