



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 27180



WO #: 27180

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11313
 Stock Desc: 2026 TT KZ-RV CONNECT 261RB
 Model: 261RB
 Serial #: 4EZTL2727T4043110
 Chassis #:
 Mileage: 0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 18 MAY 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 20 MAY 26
 Warr. Date:

Job #1 - Warranty

COMPLAINT: BEDROOM LIGHT SWITCH IS UP SIDE DOWN

CAUSE: NOTED ON DAF

CORRECTION: REMOVE LIGHT SWITCH AND INSTALL IN CORRECT POSITION

LABOR .30

Labor

Job #	Description	Hours	Total
1	INSTALLED IN CORRECT POSTION	0.30	52.50
Subtotal for Job #1:			52.50

Job #2 - Warranty

COMPLAINT: HOLES AND STAINS ON THE PANRTY WALL

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, FILL, COLOR AND BLEND AREAS

LABOR .20

Labor

Job #	Description	Hours	Total
2	FILLED AND COLORED	0.20	35.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	5.99	5.99
Subtotal for Job #2:				40.99

Job #3 - Warranty

COMPLAINT: BATHROOM CABINET DOOR TO THE LEFT OF THE MIRROR IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA

LABOR .10

Labor

Job #	Description	Hours	Total
3	FILL COLOR AND BLENDED	0.30	52.50

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



Subtotal for Job #3: 52.50

W/O: 27180

Parts Total:	0.00
Labour Total:	140.00
Sublet Total:	0.00
Extras Total:	5.99
WORK ORDER TOTAL:	145.99

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 20 May 2026

Customer Work Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

