



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27212



WO #: 27212

Customer: 49109 - HILL, PAUL
Address: 1444 WINDFIELD DRIVE
MORRISTOWN, TN
37813

Home Phone: (423) 748-4521

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11320
Stock Desc: 2026 TT FOREST RIVER
ROCKWOOD MINI 2523MBR
Model: 2523MBR
Serial #: 4X4TRLB28TZ202372
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 28 MAY 26
Date In: 27 MAY 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 28 MAY 26

Job #1 - Warranty

COMPLAINT: THERE IS A NIC IN THE WALL TRIM GOING INTO THE BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SEVERAL NAIL HOLES NOT FILLED IN ON THE LIVING ROOM SLIDE. THIS IS ON BOTH SIDES AND ACROSS THE TOP.

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREAS
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SMALL PUNCTURE IN PANTRY DOOR, KITCHEN AREA

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .10

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CRACK ON THE TOP OF THE CABINET DOOR IN THE BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Customer #: 49109
HILL, PAUL



Subtotal for Job #4: 0.00

W/O: 27212

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 27 May 2026



Customer Work Order

Customer #: 49109
HILL, PAUL

