



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 65589

### CUSTOMER WORK ORDER

WO #: 65589

Customer: 46875 - CHUBBY CHOW  
FACTORY LLC - 812-455-2400

Tag:

Author: TWK

Location: 1104 CHECK WORK

Stock #: 2201R

Stock Desc: 2022 C COACHMEN

FREELANDER 27QB

Chassis #: 1FDWE3FN9MDC39007

Serial #: 5ZTCFLS09NW427979

Mileage: 10692

Licence:

Invoice #: 370290

Date In: 26 OCT 21

Promised:

Date Sched:

Completed: 09 NOV 21

Warr. Date:

#### Job #OILC - External

OIL, LUBE, AND FILTER ON CHEVY GAS CHASSIS

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

#### Parts

Part #	Description	Qty	Price	Total
CQ620	5W30 OILX	8.00	N/C	N/C
FL820S	OIL FILTER/FL820S	1.00	N/C	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #OILC: 0.00

#### Job #1 - Warranty

COMPLAINT: WATER HEATER IS LEAKING.

CAUSE: FITTINGS LEAKING

CORRECTION: I FOUND THAT THE WATER FITTINGS ON THE BACK OF THE WATER HEATER WERE LOOSE. I TIGHTENED THE FITTINGS AND IT STOPPED LEAKING.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	78.00

#### Parts

Part #	Description	Qty	Price	Total
10-7150	CONE WASHER SWIVEL	1.00	0.24	0.24

Subtotal for Job #1: 78.24

#### Job #2 - Warranty

COMPLAINT: THERMAL FUSE ON WATER HEATER HAS BLOWN

CAUSE: FAILURE OF A PART

CORRECTION: REPLACE PART

#### Labor



Customer #: 46875  
CHUBBY CHOW FACTORY



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	32.50

**Parts**

Part #	Description	Qty	Price	Total
BRV140150	93866 THERMAL CUT-	1.00	15.35	15.35

**Subtotal for Job #2: 47.85**

Parts Total:	15.59
Labour Total:	110.50
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>126.09</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 22 Nov 2021

W/O: 65589



Customer #: 46875  
CHUBBY CHOW FACTORY

