

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 65592

Completed : 31 DEC 21
 Licence # :
 Stock No : 2101R
 Tag :
 Author : BJW
 Location : 0105 FIND OUT FROM
 Serial# : 4YDT1801XMW107834
 Warr. Date :
 Print Date : 08 JAN 22

Customer : 1013 - KEYSTONE RV CO -
 Invoice # :
 Description : 2021 TT KEYSTONE SPRINGDALE 1800BH
 Date In : 26 OCT 21 Mileage : 0
 Promised : 31 DEC 21
 Date Sched :
 Chassis# : 4YDT1801XMW107834
 Cust PO# :

 Job # Description JOB INFORMATION Type Bill To

 1 COMPLAINT: BLACK TANK IS LEAKING WITH VALVE CLOSED W 1013 KEYST
 CORRECTION: CHECKED BLACK TANK. IT WAS LEAKING AT
 THE VALVE. DRAINED TANKS AND REMOVED
 VALVE. GLUE HAD RUN OVER THE VALVE SEALS
 AND INTO THE VALVE. I TRYED TO REMOVE
 THE GLUE. IT WOULD NOT COME OFF OF THE
 VALVE. I INSTALLED A NEW VALVE.
 2 COMPLAINT: AWNING GOES OUT TOO FAR, AND WILL NOT W 1013 KEYST
 RETRACT.
 CORRECTION: LOOKS LIKE THE AWNING IS TOO LONG AND
 LETTING THE ARMS EXTEND PAST WHERE THEY
 SHOULD STOP. NEED TO GET A AWNING CANCAS
 THAT WILL NOT LET THE ARMS GO OUT SO
 FAR.
 3 COMPLAINT: WITH THE FABRIC BEING TOO LONG AFTER USE W 1013 KEYST
 IT IS NOW BENT
 CAUSE: THE FABRIC IS TOO LONG AND BUSTED THE
 BOLTS ON THAT AWNING
 CORRECTION: REPLACED AWNING AND AWNING HARDWARE.

 Job # Part No Description PARTS Bill to Qty Price Total

 1 24449 3" WASTE VALVE W-1013 1 11.88 11.88
 2 623622 Awning - Fabric On W-1013 1 291.48 291.48
 3 655276 Awning - Hardware W-1013 1 333.02 333.02

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 Z990 MISCELLANEOUS REPAIR GAH W-1013 0.50 130.00 65.00
 2 Z990 MISCELLANEOUS REPAIR GAH W-1013 2.00 130.00 260.00
 2 Z990 MISCELLANEOUS REPAIR GAH W-1013 0.00 130.00 0.00
 3 Z990 MISCELLANEOUS REPAIR GAH W-1013 0.00 130.00 0.00

Continued on page 2

Work Order : 65592

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
   3  Z990      MISCELLANEOUS REPAIR  GAH  W-1013      1.50  130.00  195.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
   2  FRT      UPS-AWN FABRIC  W-1013  1.00  92.45  92.45
   3  FRT      UPS-HARDWARE    W-1013  1.00  72.45  72.45
*****
```

CUSTOMER COMMENTS

```
*****
HARDWARE ORDERED 12-13-21...CAM
AWNING FABRIC ARRIVED IN SHOP 1A 12-8-21...CAM
PER RYAN @ LIPPERT YOU CANNOT GET THE ARMS THAT ATTACH TO THE
SIDE OF THE CAMPER BY THEMSELVES. YOU MUST ORDER COMPLETE
HARDWARE TO GET THE PARTS THAT ARE BROKEN. 12-7-21
BH GAVE PARTS SHEET TO MATT
BH GOT APPROVEL FOR INNNER AWNING ARMS
GREG FOUND TWO SMALL HOLES IN NEW FABRIC AFTER INSTALL. FILED
RGA#200115. NEW ORDER #5082060
BH SENT IN PREAUTH FOR JOB 3 11-29
AWN FABRIC IN SHOP 1A 11-22-21...CAM
ORDERED FABRIC PER BEN.
BH SENT IN PREAUTH FOR KEYSTONE 11-12
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1013        636.38  520.00  0.00   164.90  0.00  1,321.28
Totals      636.38  520.00  0.00   164.90  0.00  1,321.28
*****
```