



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65616
Promised Date: 30 APR 22

CUSTOMER WORK ORDER

WO #: 65616 (Appointment Date: 28 OCT 2021 - Time: 07:00am)

Customer: 50919 - EWELL, KEVIN -
618-982-2893

Tag:

Author: BJW

Location: 0426 CALL CUSTOMER TO
SET APPT

Stock #: 10512

Stock Desc: 2020 5W KEYSTONE
MONTANA 3781RL

Chassis #: 4YDF37829L4702716

Serial #: 4YDF37829L4702716

Mileage: 0

Licence:

Invoice #:

Date In: 28 OCT 21

Promised: 30 APR 22

Date Sched:

Completed: 30 APR 22

Warr. Date: 24 FEB 21

Job #1 - Warranty

COMPLAINT: CUSTOMER ATTEMPTED TO WINTERIZE UNIT. HE GOT ALL COMPLETED EXCEPT THE ICE MARKER. ONCE HE GOT TO THE ICE MAKER, THE PUMP CONTINUED TO RUN AND IT WOULD NOT PRIME.

CORRECTION: WINTERIZED SIDE OF PLUMBING HAD A BAD THREE WAY VALVE SO IT WAS WARRANTIED OUT. FRIDGE MADE PINK ICE CHECK PICTURES NO LEAKS. AND NOW IT PRIMES USED 4 GALLONS OF ANTI-FREEZE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	65.00

Parts

Part #	Description	Qty	Price	Total
467432	Valve - 3 Way - 1/	1.00	5.55	5.55

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 70.55

Job #2 - Internal

COMPLAINT: CUSTOMER STATES THAT THE MOTION LIGHT THAT IS NEAR THE STEPS STOPPED WORKING.

CORRECTION: mouse chewed on wires . all wires he chewed on are fixed and motion light works 2 GALLONS OF ANTIFREEZE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THERE IS A CRACK IN THE WALL TOWARDS THE REAR OF THE DINING ROOM SLIDE.

CORRECTION: TOOK PICS AND ORDERED PANEL. 11/4/21

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Printed On: 5/13/2022 9:11:43AM

© 2022 Integrated Dealer Systems



Page 1 of 2

Customer #: 50919
EWELL, KEVIN



Z990	MISCELLANEOUS REPAIR	BB	130.00
Z990	MISCELLANEOUS REPAIR	BB	130.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	260.00

Parts

Part #	Description	Qty	Price	Total
6447	Seam - Tape - 1" -	25.00	0.14	3.50
6269	Panel - 2.7mm x 48	1.00	56.35	56.35

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAM TAPE	1.00	11.76	11.76
FRT	UPS FREIGHT & CRATE - PANEL	1.00	122.45	122.45

Subtotal for Job #3: 714.06

Parts Total: 65.40
 Labour Total: 585.00
 Sublet Total: 0.00
 Extras Total: 134.21
WORK ORDER TOTAL: 784.61

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 May 2022

