

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 65626
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 51817 - THOMAS R. VINSON
Address: 250 LYNN RD MORGANFIELD, KY

42437

Phone: 270-952-6068

Stock Number: 10790 - 2021 MONTANA 3763BP 4YDF37629M4702526

VIN: 4YDF37629M4702526 HIN: SER#: 4YDF37629M4702526

Mileage: 0 Work Order Comp: 30 NOV 21

Auth. No: Dealer #: 1194

Warr. Date: 28 AUG 21 Work Order Date: 28 OCT 21 Inv #: 371130

WO # Job # Description JOB INFORMATION

65626 2 LOVESEAT RECLINER CATCHES WHEN CLOSING. BRANDON WAS SHOWN BY
CUSTOMER
love seat recliner catches when closing. brandon was shown by
customer.
Checked operation of living room recliner. Checked left side
recliner (When facing recliner). One side of foot rest does not
close all the way because it is hitting the bottom of arm rest.
The whole arm rest floats as it is not connected to floor.
Checked the other recliner. It also hits the bottom of the arm
rest, but not as bad. Need to have approval from Keystone before
replacing the recliners.

Part No Job# Description PARTS Qty Price Total

677331 2 Sofa - RA Recliner 1.00 936.27 936.27

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.00 130.00 0.00
Z990 2 MISCELLANEOUS REPAIR 0.50 130.00 65.00
Z990 2 MISCELLANEOUS REPAIR 0.00 130.00 0.00

Excode Job# Description EXTRAS Qty Price Total

FRT 2 CRATE FEE 1.00 50.00 50.00

Claim : 65626

```
*****
Excode   Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       2    FREIGHT                      1.00     175.02     175.02
```

```
Parts Total:      936.27
Labour Total:      65.00
Sublet Total:       0.00
Extras Total:      225.02
```

>>>> Claim Total: 1,226.29

Customer Signature: _____

Date: _____