

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65985

Completed : 10 FEB 22 Customer : 1013 - KEYSTONE RV CO -
Licence # : Invoice # :
Stock No : 10716 Description : 2022 TT KEYSTONE SPRINGDALE 303BH
Tag : Date In : 27 NOV 21 Mileage : 0
Author : BH Promised :
Location : 0301 CHECK WORK Date Sched :
Serial# : 4YDTSGP24N3100385 Chassis# : 4YDTSGP24N3100385
Warr. Date : 09 OCT 21 Cust PO# :
Print Date : 10 FEB 22

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: MEDICINE CABINET MIRROR FELL OFF AND W 1013 KEYST
DAMAGED THE BATHROOM SINK COUNTERTOP AND
REAR WALL PANEL AND THE METAL DOOR
THRESHOLD .

CAUSE: removed old medicine cabinet it had no
mirror when replacing installed new
mirror

CORRECTION: TOOK PICS AND MEAURMENTS FOR BEN. REMOVE
TOILET. REMOVE CABINET DOOR. REMOVE
DRAIN. REMOVE COUNTER TOP.REMOVE FAUCET.
INSTALL FAUCET ON NEW COUNTER TOP.
INSTALL NEW COUNTER. HOOK UP PLUMBING .
SILICONE SINK AND COUNTER TOP. REMOVE
WALL TRIM. REMOVE WALL PANEL. CUT NEW
WALL PANEL AND INSTALL. PUT ON NEW TRIM
AND PUTTY HOLES. PUT BACK TOILET. PUT ON
NEW THRESHOLD TRIM.

2 COMPLAINT: OUTSIDE AWNING LIGHT WON'T COME ON W 1013 KEYST
SOMETIMES THEY WORK AND SOMETIMES THEY
DONT

CORRECTION: FOUND LOOSE WIRE ON AWNING LIGHTS.
COULDN'T TAKE A PIC. JUST FIXED IT

Job # Part No Description PARTS Bill to Qty Price Total

1	657147	MEDICINE CABINET -	W-1013	1	48.19	48.19
1	6495	Panel - 2.7mm x 48	W-1013	1	59.78	59.78
1	6496	Trim - Batten - 3.	W-1013	3	2.25	6.75
1	674277	LAVTOP-20X15 SPRIN	W-1013	1	7.10	7.10
1	383836	26" LCI ENTRY DOOR	W-1013	1	5.55	5.55

Continued on page 2

Work Order : 65985

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
  1 Z990  MISCELLANEOUS REPAIR  SAR  W-1013    0.50   130.00    65.00
  1 Z990  MISCELLANEOUS REPAIR  BB   W-1013    0.50   130.00    65.00
  1 Z990  MISCELLANEOUS REPAIR  BB   W-1013    1.50   150.00   225.00
  1 Z990  MISCELLANEOUS REPAIR  BB   W-1013    1.50   150.00   225.00
  2 Z990  MISCELLANEOUS REPAIR  BB   W-1013    0.20   130.00    26.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to    Qty    Price    Total
*****
  1 FRT  UPS-MEDICINE CABINET  W-1013    1.00    29.47    29.47
  1 FRT  FREIGHT & CRATE - PANELING W-1013    1.00   122.45   122.45
  1 FRT  UPS-COUNTERTOP      W-1013    1.00    15.69    15.69
  1 FRT  UPS-THRESHOLD       W-1013    1.00    12.38    12.38
*****
```

CUSTOMER COMMENTS

PARTS MOVED TO RED TRAILER 1-18-22...CAM

DOOR THRESHOLD IN BACKROOM 12-29-21...CAM

COUNTERTOP ARRIVED. 12-15-21 MAB

PANELING, TRIM, AND BLACK PLASTIC COVER IN SHOP 1A 12-13-21...CAM

MEDICINE CABINET IN BACKROOM 12-10-21...CAM

ORDERED ALL PARTS 12-3-21 @ 10:45 A.M. ORDER#5087049

BH GAVE PARTS SHEET TO MATT

BH GOT APPROVAL FOR BOTH

BH SENT IN PREAUTH FOR JOB2

BH SENT IN PREAUTH FOR JOB1

BILLINGS SUMMARY

```
*****
Type Bill Id    Parts  Labour  Sublet  Extras    Tax    Total
*****
W      1013      127.37  606.00   0.00   179.99    0.00    913.36
      Totals      127.37  606.00   0.00   179.99    0.00    913.36
*****
```