

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12867

Date In: 30 SEP 25 Author: MGRAY  
Promised Date: 31 DEC 25 Stock No:  
: Year: 2018  
Customer Name: 7439 - JANZ, TIM Manufacturer: FLAGSTAFF MICRO  
Address: 3584 TOWN HALL RD Brand: FLAGSTAFF MICRO  
: JUNCTION CITY, WI Model: 21FBR5  
Postal/Zip: 54443 Miles/Hrs:  
Phone#(res): 715-204-6553 Exterior Color:  
Phone#(bus): Unit Type:  
Cell Phone: 715-457-3273 License#:  
Email: THEJANZFAMILY@GMAIL.CO Tag#: apt 10/7  
Purchased Date: :  
Delivery Date: :  
InService Date: :  
Serial#: 4X4TFL027JD420468 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
RI COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF I PD GOODW  
REPAIR IS NEEDED.  
CAUSE: Request roof inspection  
CORRECTION: Indpected rooftop, examined membrane,  
sealants and fixtures. Membrane is in  
good condition, free of any damage,  
sealants are somewhat dirty looking, but  
resembles its age, sealants are free of  
shrinkage, some slight dry-cracking,  
nothing concerning. still sufficient to  
withhold moisture penetration, fixtures  
are in good condition, no evidence of  
damage or leaking. Inspect sealants next  
season for possible refreshing. No  
further action necessary at this time.  
BBI COMPLAINT: BRAKE AND BEARING INSPECTION E 7439 JANZ  
CAUSE: Request BBI - Wheel hubs were  
Over-greased at some point. Grease  
pushed through axle seal coating brake  
components. Highly recommend replacement  
of Brake hub assemblies x4, new axle  
seals required, clean and repack bearing  
need to be done too. Grease is black and  
spent. (6.5hrs) dexter axles and  
components 2.25"x10"  
CORRECTION: Done

Continued on page 2

Work Order : 12867

```
*****
Job # Part No      Description      PARTS    Bill to    Qty      Price      Total
*****
BBI  EST          5723468 - Brake Assembly E-7439    0         0.00        0.00
BBI  EST          5723469 - Brake Assembly E-7439    0         0.00        0.00
BBI  82203510214  Dexter 3,500 lb Axle NEV E-7439    2        220.05       440.10
BBI  711217012464 WHEEL SEAL                E-7439    4         5.23        20.92
*****
```

```
*****
Job#  Lab Code  Description      LABOUR    Mech Bill to    Hrs      Rate      Total
*****
RI  Z991      PREFORM ROOF INSPECTIO RW    I-PD      0.30     70.00     21.00
BBI BBI      BEARING BRAKE INSPECTI RW    E-7439    0.50    140.00     70.00
BBI R735     BEARINGS, PACK (TANDEM JL    E-7439    3.05    130.00    396.50
BBI R735     BEARINGS, PACK (TANDEM JL    E-7439    0.00    130.00        0.00
BBI R735     BEARINGS, PACK (TANDEM JL    E-7439    0.24    130.00     31.20
BBI R735     BEARINGS, PACK (TANDEM JL    E-7439    0.79    130.00    102.70
BBI R735     BEARINGS, PACK (TANDEM JL    E-7439    1.04    130.00    135.20
BBI R735     BEARINGS, PACK (TANDEM JL    E-7439    0.88    130.00    114.40
*****
```

```
*****
Job #  Excode  Description      EXTRAS    bill to    Qty      Price      Total
*****
BBI  SSE      SHOP SUPPLIES - EXTERNAL    E-7439    1.00     35.00     35.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E    7439          461.02      850.00      0.00      35.00      74.10     1,420.12
I    PD           0.00        21.00      0.00      0.00        0.00        21.00

Totals          461.02      871.00      0.00      35.00      74.10     1,441.12
*****
```

&k2S  
&k0S