

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville IN  
 US  
 47725  
 812-867-5200

WORK ORDER # 66039

Completed : 27 DEC 21 Customer : 1013 - KEYSTONE RV CO -  
 Licence # : Invoice # :  
 Stock No : 10721 Description : 2021 5W KEYSTONE SPRINGDALE 300FWBH  
 Tag : Date In : 03 DEC 21 Mileage : 0  
 Author : BH Promised :  
 Location : 1227 CHECK PARTS Date Sched :  
 Serial# : 4YDF30028M3106779 Chassis# : 4YDF30028M3106779  
 Warr. Date : 14 MAY 21 Cust PO# :  
 Print Date : 27 DEC 21

```

*****
Job # Description JOB INFORMATION Type Bill To
*****
1 COMPLAINT: WATER PUMP IS CYCLING WHEN HOOKED UP TO W 1013 KEYST
  THE CITY WATER IT KICKS WATER TO THE
  FRESH WATER TANK.
  CORRECTION: CHECKED THE SYSTEM THE WATER PUMP MIGHT
  HAVE A BAD CHECK VALVE SINCE WATER
  PASSES THROUGH WHEN IT SHOULDNT
2 COMPLAINT: THE DVD RADIO THE PUSH BUTTONS ARE NOT W 28810 ASA E
  WORKING
  CORRECTION: INSPECTED RADIO DVD PLAYER BUTTONS DO
  NOT WORK ON THE FACE OF RADIO
RECA COMPLAINT: LP REGULATOR RECALL #21-414 W 1013 KEYST
  CAUSE:
  CORRECTION: UNIT DOESNT HAVE THE DEFECTIVE LP
  REGULATOR OK FOR USE
3 COMPLAINT: TRIM ON INSIDE OF DOOR LEFT SIDE OF DOOR W 1013 KEYST
  WAY NEED REATTACHED
  CORRECTION: restapled the trim and used putty
  
```

```

*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
1 186592 (KEYSTONE) FLOJET W-1013 1 46.43 46.43
  
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
1 Z990 MISCELLANEOUS REPAIR W-1013 0.00 130.00 0.00
1 Z990 MISCELLANEOUS REPAIR SAR W-1013 0.30 130.00 39.00
1 Z990 MISCELLANEOUS REPAIR SAR W-1013 0.00 130.00 0.00
2 Z990 MISCELLANEOUS REPAIR W-28810 0.00 130.00 0.00
2 Z990 MISCELLANEOUS REPAIR SAR W-28810 0.40 130.00 52.00
2 Z990 MISCELLANEOUS REPAIR SAR W-28810 0.00 130.00 0.00
2 Z990 MISC LABOUR CODE (EXTE SAR W-28810 0.30 130.00 39.00
CALL Z990 MISCELLANEOUS REPAIR SAR W-1013 0.30 130.00 39.00
  
```

Continued on page 2

Work Order : 66039

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
   3  Z990      MISCELLANEOUS REPAIR          W-1013    0.00  130.00    0.00
   3  Z990      MISCELLANEOUS REPAIR    SAR  W-1013    0.00  130.00    0.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
   1  SS      SHOP SUPPLIES          W-1013    1.00    0.00    0.00
   1  FRT      UPS-PUMP                W-1013    1.00   13.89   13.89
*****
```

CUSTOMER COMMENTS

```
*****
RADIO PAYS .7 PER ASA.
RADIO BOXED AND READY TO SHIP BACK TO ASA.
TRACKING#1ZAE70560600259349. WE WILL SHIP BACK ON 12-20-21. MAB
PUMP IN BACK ROOM. 12-16-21
WAITING FOR SHAWN TO GET A SERIAL# FOR THE RADIO. WILL FILE
THROUGH ASA WHEN HE GETS IT.
ORDERED PUMP 12-14-21.
BH SENT IN FOR PREAUTH FOR WATER PUMP AND RADIO
KEYSTONE TOLD US TO GO TO ASA FOR THE RADIO
BH GAVE PARTS SHEET TO MATT
BH SENT IN PREAUTH FOR RECALL THEY DENIED BH SENT IN FOR CLAIM
12-14
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W      1013      46.43   78.00   0.00   13.89  0.00   138.32
W      28810     0.00   91.00   0.00   0.00  0.00    91.00
Totals      46.43  169.00   0.00   13.89  0.00   229.32
*****
```