

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 899898 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2CKFC6MY014973 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 017 / 017D <b>ITEM #</b> CKTR17JG-D <b>DEALER RO #</b> 66060 <b>CLAIM START DATE</b> 01/18/2022 <b>CLAIM END DATE</b> 01/01/1900
<b>Labor rate:</b> \$150.00 <b>OWNER INFORMATION</b> WILLIAM GOEDDE 1669 E 1025 S Haubstadt, IN 47639 USA	<b>Retail Date of Purchase</b> 04/29/2021 <b>WARRANTY EXPIRATION DATE</b> 04/29/2022

## Claim Line Details

**Labor**

<b>Line# 1</b>	<b>Operation Code</b> 30-103-24-00-001125	<b>Operational Description</b> Linoleum - Interior/Flooring/Repair/No Tread Code	
	<b>Complaint, Cause, Correction</b> Original Note : bhoffman@americanrvcenter.com, 2022-01-18 09:39:23 :: A BOX NEAR THE WHEEL WELL FELL DOWN AND NEEDS TO BE PUT BACK UP AND FOR THE SLIDE IT IS ACTING LIKE IT IS AMPING OUT FOUND BOX UNDER THE SLIDE ROOM AND FOUND THE LINO TORE UP NEED TO PUT BOX BACK AND REPLACE THE LINO THAT IT TORE UP		
	<b>Model #</b>	<b>Dlr Sub Hrs</b> 4.00	<b>Sub Labor Amt</b> \$600.00
	<b>Serial #</b>	<b>Appr Hrs</b> 4.00	<b>Appr Labor Amt</b> \$600.00
	<b>Notes</b>		

<b>Submitted</b>	<b>Labor Amt</b> \$600.00	<b>Approved</b>	<b>Labor Amt</b> \$600.00
	<b>Parts &amp; Freight</b> \$0.00		<b>Parts &amp; Freight</b> \$0.00
	<b>Total</b> \$600.00		<b>Total</b> \$600.00

\_\_\_\_\_  
**DEALER** **DATE**  
**SIGNATURE**  
I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER** **DATE**  
**SIGNATURE**  
All repairs described have been inspected and are satisfactory.