

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2687343
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRRB6TB526603
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT255DS
		DEALER RO #	73400
		CLAIM START DATE	05/26/2026
		CLAIM END DATE	05/27/2026

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	10-17-24-00-000304	Diamond Plate - Frame & Chassis/Specialty, Utility Unit/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-26 12:23:16 :: Complaint: Front diamond plate is loose			
	Cause: Not secured properly/separated Correction: Removed left and right corner moldings. Repositioned and			
	reinstalled metal. Reinstalled left and right corner moldings. Sealed. Added screws to metal to secure in place.			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$190.00	
Serial#	Appr Hrs	1.00	Appr Labor Amt \$190.00	
Notes				
Authed				

Submitted	Labor Amt	\$190.00	Approved	Labor Amt	\$190.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$190.00		Total	\$190.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.