

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville IN  
 US  
 47725  
 812-867-5200

WORK ORDER # 66100

Completed : 30 DEC 21 Customer : 10024 - FOREST RIVER TRAVEL TRAILER  
 Licence # : Invoice # :  
 Stock No : 10677 Description : 2022 TT COACHMEN CATALINA 263BHCKL  
 Tag : Date In : 14 DEC 21 Mileage :  
 Author : DH Promised :  
 Location : 01 RESV WORK Date Sched :  
 Serial# : 5ZT2CARB9NU039758 Chassis# : 5ZT2CARB9NU039758  
 Warr. Date : Cust PO# :  
 Print Date : 03 JAN 22

\*\*\*\*\*  
 Job # Description JOB INFORMATION Type Bill To  
 \*\*\*\*\*

PDIN COMPLAINT: PDI - NEW TRAVEL TRAILER I PDI PRE-D  
 CAUSE: pdi  
 CORRECTION: checked water system, electrical,  
 plumbing, brakes, running lights, inside  
 and outside lights, filled lp tanks, ran  
 lp leak test, checked tire pressure,  
 drained all holding tanks,  
 1 COMPLAINT: SILICONE ON WINDOWS & DOOR ON PASSANGER W 10024 FORES  
 SIDE  
 CAUSE: SILICONE ON WINDOW AND DOOR.  
 CORRECTION: REMOVED WITH ADHESIVE REMOVER  
 2 COMPLAINT: BEDROOM CLOSET DOOR WONT LATCH W 10024 FORES  
 CAUSE: closet door wont latch  
 CORRECTION: removed latch and sanded hole where  
 latch goes into the frame so icould  
 adjust it. installed latch  
 3 COMPLAINT: CABINET DOOR ABOVE BED & (DOORLATCH) W 10024 FORES  
 NEEDS ADJ  
 CAUSE: latch for cabinet is off center  
 CORRECTION: removed latch and moved it down so it  
 would catch. filled original holes with  
 putty  
 4 COMPLAINT: CHECK VALVE FOR THE BLACK TANK FLUSH IS W 10024 FORES  
 BROKEN NEED REPLACED  
 CAUSE: check valve leaking and water line was  
 kincked.  
 CORRECTION: replaced check valve and installed a 90  
 degree hose fitting

\*\*\*\*\*  
 Job # Part No Description PARTS Bill to Qty Price Total  
 \*\*\*\*\*  
 PDINT 13034 55362 STD BATTERY BOX I-PDI 1 10.95 10.95  
 4 282770 94239 VACUUM BREAK W-10024 1 21.72 21.72

Continued on page 2

Work Order : 66100

```
*****
Job # Part No Description          PARTS          Bill to  Qty    Price    Total
*****
4      10-7150 CONE WASHER SWIVEL          W-10024    1      0.24     0.24
4      10-0927 1/2" BARB FITTING           W-10024    1      2.04     2.04
PDINT 24181  -50 RV ANTI-FREEZE GALLON      I-PDI      2      4.99     9.98
*****
```

```
*****
Job# Lab Code Description          LABOUR    Mech Bill to  Hrs    Rate    Total
*****
DINTT Z991      MISC LABOUR CODE (INTE ZMS I-PDI      0.00   130.00    0.00
DINTT Z991      MISC LABOUR CODE (INTE ZMS I-PDI      1.05   130.00   136.50
DINTT Z991      MISC LABOUR CODE (INTE ZMS I-PDI      3.74   130.00   486.20
DINTT Z991      MISC LABOUR CODE (INTE ZMS I-PDI      1.21   130.00   157.30
      1 Z990      MISC LABOUR CODE (EXTE ZMS W-10024    0.20   130.00    26.00
      2 Z990      MISC LABOUR CODE (EXTE ZMS W-10024    0.20   130.00    26.00
      3 Z990      MISC LABOUR CODE (EXTE ZMS W-10024    0.30   130.00    39.00
      4 Z990      MISC LABOUR CODE (EXTE ZMS W-10024    0.30   130.00    39.00
*****
```

```
*****
Job # Excode Description          EXTRAS          bill to  Qty    Price    Total
*****
DINTT SS        SHOP SUPPLIES          I-PDI      1.00   35.00    35.00
DINTT LPGI      LP - UNIT SALES        I-PDI      8.00    3.99    31.92
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      PDI      20.93    780.00    0.00     66.92    0.00    867.85
W      10024    24.00    130.00    0.00     0.00     0.00    154.00
      Totals    44.93    910.00    0.00     66.92    0.00    1,021.85
*****
```