



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72590
 Promised Date:
 22 NOV 25



WO #: 72590 (Appointment Date: 22 OCT 2025 - Time: 01:15pm)
 Customer Name: 52773 - GABALDON, GARY
 Completed Date:
 Invoice#:
 Author: ADVISOR
 Stock Desc: 2021 GALLERIA GAB24AM
 Serial#:
 Chassis#: W1X8ED3Y3KP194403
 Miles/Hrs: 28054
 Tag#: 6872
 Purchased Date:
 Warranty Date:

Date In: 22 OCT 25
 Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES AWNING CAME OUT ON ITS OWN/ RECALL ON THE AWNING.

CAUSE: Awning opened on its own while driving will not roll back up.
 See pictures.

CORRECTION: Recall diag completed

Labor

Job #	Description	Total
1	AWNING	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 16 Dec 2025

Customer #: 52773
 GABALDON, GARY

