



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 27156



WO #: 27156

Customer: 89897 - STONE, CARL
 Address: 865 HICKORY COVE RD
 ROGERSVILLE, TN
 37857

Home Phone: 423-523-2542

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11070

Stock Desc: 2025 FW FOREST RIVER CEDAR

CREEK 33BH

Model: 33BH

Serial #: 4X4FCRJ21SS234381

Chassis #:

Mileage:

Key #: 9750

Req'n #:

License #:

Trim:

Purchase Date: 19 MAY 26

Date In: 13 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 08 JUN 26

Warr. Date: 16 MAY 26

Job #1 - Warranty

COMPLAINT: FRIDGE KEEPS BLOWING 40 AMP FUSES AND TECH CAN HEAR THE BOARD SIZZLE WHEN THIS HAPPENS

CAUSE: TECH STATED THE BOARD HAS CORROSION ON THE BOARD AND CONFIRMS IT KEEPS BLOWING 40 AMP FUSES
 TECH CONFIRMS FRIDGE IS COOLING

CORRECTION: REPLACE BOARD ON FRIDGE AND TEST
 LABOR WITH DIAG 1.0

Labor

Job #	Description	Hours	Total
1	REPLACED BOARD AND TESTED	0.70	122.50

Parts

Part #	Description	Qty	Price	Total
F100722320	REFRIGERATOR, PART, MAIN CONTROL PANEL/BOARD, GENERATION 2.0, REPLACEMENT FOR FURRIION FCR20DCAFA [GA10] V#2025014800 (9A-SOP)	1.00	295.85	295.85

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	27.38	27.38

Subtotal for Job #1: 445.73

Parts Total: 295.85
 Labour Total: 122.50
 Sublet Total: 0.00
 Extras Total: 27.38
WORK ORDER TOTAL: 445.73

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 89897
 STONE, CARL



Customer Signature : _____

Date: 08 Jun 2026

W/O: 27156

Customer Work Order



Customer #: 89897
STONE, CARL

