

# K-Z CHECK IN FORM

DATE: 6-6-26

TECH: JD

STOCK# 11322

2027

53771

Connect SE

301BHKSE

YEAR

VIN

BRAND

MODEL

## ITEMS TO BE CORRECTED:

- ① Floor in front of stove squeaks and goes down in a spot
- ② Main Bathroom door damaged @ bottom and chipped up from that.
- ③ Trim above bunk door scratched
- ④ Bunk room door damaged on side down to wood grain, several scratches
- ⑤ Main Bedroom door scratched/damaged several areas
- ⑥ Missing bumper plug/cover
- ⑦ Chips in cabinet door above TV area (living)

K. Z., Inc.  
 0985 N 900 W  
 Shipshewana, IN 46565  
 driversheets@kz-rv.com

Dealer: TRI-AM RV CENTER OF EAST  
 TENNESSEE, INC.  
 1202 IDELL ROAD  
 BULLS GAP, TN 37711  
 USA

Model 2027 Connect SE C301BHKSE  
 Run# 460628  
 VIN 4EZTL3120V4053771  
 Invoice# KZIN016630  
 Invoice-Date: 5/21/2026  
 SO# SO0019910

PO#

**DRIVER INSTRUCTIONS:**

1. Verify the serial numbers to be certain the invoiced unit and shipped unit are the same
2. Torque the lug nuts
3. Check the unit to assure there is neither exterior nor interior damage
4. Verify that all keys are in the unit
5. Assure any identified damages have been repaired before taking the unit

**I have completed the above items and all is satisfactory.**

**On behalf of the dealer with which I have/my firm has contracted to deliver the unit referenced hereon, I hereby affirm that I have taken possession of the unit and accept all risk of loss effective the date signed below.**

J. PLANK

Driver

MOR

Transport Company Name

5-26-26

Date

**I hereby certify that I am not an employee or otherwise a legal representative of the dealership by which I or my firm has been hired to transport the RV referenced on this form.**

**DEALER INSTRUCTIONS**

Check the unit for damage and items that are invoiced but not on the unit. Any discrepancies must be listed and verified by the driver, as the driver is responsible for damage incurred, and for items which are not on the unit when he accepted it from the plant and not on it when you receive it. If you have none, **PLEASE WRITE NONE.**

**SHORTAGES**

**DAMAGES**

Missing Bumper  
 Vent IN BUNK  
 Squeak IN FLOOR  
 TRIM ABOVE Bunk DOOR scratched  
 Plug/Cover open  
 Front of stove  
 " " " "

MAIN DOOR  
 MAIN IS the BATHROOM DOOR PULLED AWAY at the Bottom  
 Bunk DOOR cracked  
 Bed Room scratched

Check Refer Door  
 Power Cord in Unit  
 Dealer Sign [Signature]  
 Date 5-27-26

Power Cord in Unit  
 Driver Sign [Signature]  
 Date 5-26-26