

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13439

Date In:	29 APR 26	Author:	DLUCAS
Promised Date:	31 MAY 26	Stock No:	11412
:	:	Year:	2026
Customer Name:	17927 - LASSA, SUSAN	Manufacturer:	FOREST RIVER
Address:	9340 S 44TH CT	Brand:	PUMA DESTINATION
:	FRANKLIN, WI	Model:	38RLB
Postal/Zip:	53132	Miles/Hrs:	0
Phone#(res):	4148400858	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	tslassa11@gmail.com	Tag#:	DB= 5/7
Purchased Date:	29 OCT 25	:	:
Delivery Date:	17 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUP20TP106347	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
SC      COMPLAINT:  CUSTOMER REQUESTS SERVICE CALL TO 1009  I    FSC    FREE
        SOUTH ARCHERS WAY ROME
        CORRECTION: COMPLETE
3      COMPLAINT:  CUSTOMER STATES KITCHEN AND BATHROOM      W    1021   FORES
        FAUCETS LEAKING
        CAUSE:      after leveling unit the exterior door
                    bor bedroom now closings correctly but I
                    also taken pictures of kitchen faucet
                    and bathroom faucet they are both
                    leaking internally
        CORRECTION: NEW FAUCETS INSTALLED AND LEAK CHECKED
1      COMPLAINT:  CUSTOMER STATES FURNACE NOT WORKING      W    1021   FORES
        RANDOMLY PLEASE DIAGNOSE
        CAUSE:      was getting 13.75 volts to furnace would
                    intermittently work found that sail
                    switch was dirty and also wouldn't light
                    after sail switch installed replaced
                    control board pics taken of parts used
        CORRECTION: after replacing the sail switch and
                    control module on furnace is working
*****
```

```
*****
Job #  Part No    Description                PARTS                Bill to    Qty    Price    Total
*****
3      F100271116 FAUCET, LAVATORY, TWO HAND W-1021          1      15.17    15.17
3      822030266  FAUCET, KITCHEN, COIL, TWO W-1021          1      61.78    61.78
*****
```

Continued on page 2

Work Order : 13439

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   3  WARR      MANUFACTURER WARRANTY  JS    W-1021    0.50   140.00    70.00
   1  DIAG      DIAGNOSTICS                JS    W-1021    1.00   140.00   140.00
   3  WARR      MANUFACTURER WARRANTY  JS    W-1021    0.50   140.00    70.00
   3  WARR      MANUFACTURER WARRANTY  JS    W-1021    0.50   140.00    70.00

```

```

*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
SC  SC          SERVICE CALL                I-FSC    15.00    3.75    56.25
   3  FRT          FREIGHT FOR BOTH FAUCETS  W-1021    1.00   39.03    39.03

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      FSC          0.00      0.00      0.00      56.25      0.00      56.25
W      1021         76.95     350.00     0.00      39.03      0.00     465.98

      Totals        76.95     350.00     0.00      95.28      0.00     522.23

```

&k2S
&k0S