

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66178
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10826 - 2022 CHEROKEE 274BRB 4X4TCKC27NX155487

VIN: 4X4TCKC27NX155487 HIN: SER#: 4X4TCKC27NX155487

Mileage: 0 Work Order Comp: 18 JAN 22

Auth. No: Dealer #:

Warr. Date: Work Order Date: 27 DEC 21 Inv #: 372184

WO # Job # Description JOB INFORMATION

66178 4 COMPARTMENT DOOR HOLDBACK NOT INSTALLED...NOTED AT CHECK-IN
door latch not installed
installed door latch

66178 1 MAIN ENTRANCE DOOR IS BOWED
DOOR IS BOWED
TOOK A PIECE OF WOOD AND TAPED IT TO THE TOP AND BOTTOM OF THE
DOOR WHERE IT MAKES CONTACT WITH THE FRAME AND PUSHED THE CENTER
OF THE DOOR TO HELP STRAIGHTEN OUT.

66178 2 MAIN ENTRANCE DOOR SCREEN IS HITTING DOOR LATCH
screen door hitting latch
moved latch over with block of wood and a hammer.

66178 3 REAR ENTRANCE DOOR SCREEN HITTING LATCH.
latch hitting screen door
moved door latch with a block of wood and a hammer

66178 5 DRIVER SIDE REAR COMP DOOR FRAME BENT. NOTED ON DEL SHEET
SCREW ON RIGHT SIDE OF WHERE THE FRAME ENDS WAS IN TOO FAR.
CAUSING A GAP.
ADDED ANOTHER SCREW TO THE LEFT SIDE AND APPLIED SILICONE TO THE
GAP IN THE MIDDLE.

66178 6 OUTSIDE STOVE WILL NOT PULL OUT
SCREW THAT HELD THE ICE MAKER IN PLACE WAS HITTING THE BURNER

