



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$165.00

RO# : 40891 Tag# : R17G0101

Check-in: Fri Jun 5, 2026 | 8:03 AM
Ready for Pickup: Tue Jun 9, 2026 | 10:02 AM
Promise Time: Wed Jun 10, 2026 | 6:00 PM

Customer
Mark Bergum
7156344737
+1 - (612) 816 - 0787
bergumeliz@gmail.com
8685 N HIGHLINE ROAD
HAYWARD, WI 54843

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2024 Jayco
JAYFLIGHT184BS
1UJBC0BM8R17G0101
2 Mi In / 2 Mi Out
Sold Date: 10/27/2025
Stock #: 24-28

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	CUSTOMER STATES UNDER KITCHEN SINK THERE IS A WATER LEAK.	Warranty Pay	\$82.50
----	---------------	---	--------------	---------

Job added by BONNIE SEEMANN on Fri Jun 5, 2026 | 8:03 AM

1. Water drip under kitchen sink.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$15.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.4	0.5	0.5	\$82.50	\$15.00

1. Found connection for pull down sprayer hose on kitchen faucet was barely finger tight. Used the double wrench method and tightened connection. Ran water through sink for 5 minutes, no further leaks detected. requesting .50 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$82.50	\$15.00	\$0.00	\$0.00

B.	MISCELLANEOUS	CUSTOMER STATES THE MAIN DOOR IS BOWED AND HAS TO BE SLAMMED FROM INSIDE AND OUTSIDE TO CLOSE.	Warranty Pay	\$82.50
----	---------------	--	--------------	---------

Job added by BONNIE SEEMANN on Fri Jun 5, 2026 | 8:03 AM

1. Check door function





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$165.00

RO# : 40891 Tag# : R17G0101

Check-in: Fri Jun 5, 2026 | 8:03 AM
Ready for Pickup: Tue Jun 9, 2026 | 10:02 AM
Promise Time: Wed Jun 10, 2026 | 6:00 PM

Customer Mark Bergum 7156344737 +1 - (612) 816 - 0787	Billing-Customer Same as Customer	Vehicle 2024 Jayco JAYFLIGHT184BS 1UJBC0BM8R17G0101	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$15.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.45	0.5	0.5	\$82.50	\$15.00

1. Door difficult to latch. Adjusted door and latch. Closes and latches with much less effort now. requesting .50 hours

Total Labor Sale \$82.50	Total Labor Cost \$15.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

C. MISCELLANEOUS	CUSTOMER STATES CHECK THE CARON MONIXE DETECTOR IT KEEPS CHURPING AT THEM AND WENT OFF ONCE WITH THE LP TANK ON	Warranty Pay	\$0.00
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Fri Jun 5, 2026 | 8:03 AM

1. Test CO detector.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$9.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.22	0.3	0.3	\$0.00	\$9.00

1. Tested CO detector. Tested good, no issues discovered. Performed LP leak check on camper just to be safe. LP drop test good (8 inches of water column sustained for 3 minutes). Let customer know if they continue to experience any further issues with their CO detector, they may need to replace it. requesting 0 hours wont charge customer

Total Labor Sale \$0.00	Total Labor Cost \$9.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$165.00

RO# : 40891 Tag# : R17G0101

Check-in: Fri Jun 5, 2026 | 8:03 AM
Ready for Pickup: Tue Jun 9, 2026 | 10:02 AM
Promise Time: Wed Jun 10, 2026 | 6:00 PM

Customer
Mark Bergum
7156344737
+1 - (612) 816 - 0787

Billing-Customer
Same as Customer

Vehicle
2024 Jayco
JAYFLIGHT184BS
1UJBC0BM8R17G0101

Service Advisor
KEVIN GOODIEL
goodielk

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$0.00	\$0.00

Category	Sale	Cost
Labor	\$165.00	\$39.00
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$165.00	\$39.00

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Mon Jun 8, 2026	11:20 AM	11:44 AM	0.40 hrs	W	shurterc	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Mon Jun 8, 2026	11:44 AM	12:11 PM	0.45 hrs	W	shurterc	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Mon Jun 8, 2026	12:13 PM	12:13 PM	0 hrs	W	shurterc	-
Tag: Regular Hour			Reason: -					
C	MISC	Mon Jun 8, 2026	12:13 PM	12:26 PM	0.22 hrs	W	shurterc	0.3 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$165.00

RO# : 40891 Tag# : R17G0101

Check-in: Fri Jun 5, 2026 | 8:03 AM
Ready for Pickup: Tue Jun 9, 2026 | 10:02 AM
Promise Time: Wed Jun 10, 2026 | 6:00 PM

Customer
Mark Bergum
7156344737
+1 - (612) 816 - 0787

Billing-Customer
Same as Customer

Vehicle
2024 Jayco
JAYFLIGHT184BS
1UJBC0BM8R17G0101

Service Advisor
KEVIN GOODIEL
goodielk

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40891	LINK RV	\$165.00
57200	40891	LINK RV	-\$165.00
67200	40891	LINK RV	\$39.00
14400	shurterc	LINK RV	-\$39.00

