

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66180
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10856 - 2022 CHEROKEE WOLF PUP 18TO 5ZT2CKGC1NY021748
VIN: 5ZT2CKGC1NY021748 HIN: SER#: 5ZT2CKGC1NY021748
Mileage: 0 Work Order Comp: 07 JAN 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 27 DEC 21 Inv #: 371979

WO # Job # Description JOB INFORMATION

66180 4 OUTSIDE KITCHEN DOOR WONT OPEN
couldnt get lock to open. tried to lubricate mechanism but
couldnt get it to move at all.
drilled out center of lock until the inside of the lock broke and
i could move the latch, replaced with a new lock.

66180 8 DOOR HOLDER NOT INSTALLED ON FRONT COMPARTMENT
door holder needs to be installed.
installed door holder on front door side compartment

66180 2 SCREEN DOOR IS CATCHING LATCH
screen door is hitting the latch for the main door, the latch for
the screen door and the door frame at the top left corner.
pushed both latches in with a small block of wood and a hammer.
pushed in the door frame where it was hitting the door with block
of wood and hammer. door is clearing latches and frame.

66180 3 LEATHER PIECE ABOVE DOOR IS BOWED OUT
need to straighten the piece out.
removed screw covers. removed piece of trim. put piece on work
bench and pushed the opposite way of the bend. took screws and re
installed piece. installed screw covers with hammer.

66180 5 TOP OF MAIN ENTRY DOOR NEEDS SILICONE
silicone missing above door
applied silicone as needed.

Claim : 66180

```

*****
WO #      Job #   Description      JOB INFORMATION
*****

```

```

66180      6   REAR WALL NEEDS SILICONE
            rear wall missing silicone
            applied silicone as needed

```

```

66180      7   STAIN ON BACK OF DINNETTE "TRIM"
            stain on trim.
            cleaned with mineral spirits

```

```

*****
Part No    Job#   Description      PARTS          Qty    Price    Total
*****
RVDL428    4   L428 1-1/8" KEYED          1.00    4.24    4.24
RVDE210    8   E210 2-pk BLK ROUN         1.00    6.54    6.54

```

```

*****
Lab Code   Job#   Description      LABOUR          Hrs    Rate    Total
*****
Z990      4   MISC LABOUR CODE (EXTERNAL)      0.10   130.00   13.00
Z990      8   MISC LABOUR CODE (EXTERNAL)      0.10   130.00   13.00
Z990      2   MISC LABOUR CODE (EXTERNAL)      0.20   130.00   26.00
Z990      3   MISC LABOUR CODE (EXTERNAL)      0.20   130.00   26.00
Z990      5   MISC LABOUR CODE (EXTERNAL)      0.20   130.00   26.00
Z990      6   MISC LABOUR CODE (EXTERNAL)      0.30   130.00   39.00
Z990      7   MISC LABOUR CODE (EXTERNAL)      0.10   130.00   13.00

```

```

Parts Total:      10.78
Labour Total:     156.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 166.78

Customer Signature: _____

Date: _____