

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
<b>BASDEN RV CENTER INC</b>		<b>CLAIM</b>	2688255
<b>DBA AMERICAN RV CENTER</b>		<b>CLAIM ORIGIN</b>	WEB
<b>600 E BASELINE ROAD</b>		<b>ORIGINAL CLAIM ID</b>	
<b>EVANSVILLE, IN 47725</b>		<b>VIN</b>	5ZT2CAVB1TX036824
<b>USA</b>		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$195.00	<b>SITE/WAREHOUSE</b>	205 / 205
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	ACAT303RKDSLE
<b>EMILY N ART</b>		<b>DEALER RO #</b>	79887
<b>118 SHADOW VALLEY LN</b>		<b>CLAIM START DATE</b>	05/26/2026
<b>Trenton, GA 30752</b>		<b>CLAIM END DATE</b>	01/01/1900
<b>USA</b>			
<b>Retail Date of Purchase</b>	05/21/2026	<b>WARRANTY EXPIRATION DATE</b>	05/21/2027

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	60-141-12-00-001560	P-Trap - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-26 16:01:24 :: P TRAP LEAKING UNDER KITCHEN SINK The fitting that connects the p trap to the sink is leaking. Tightened up fitting and filled the sink partially. Cleaned up mess. The sink is no longer leaking.			
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>0.10</b>	<b>Sub Labor Amt \$19.50</b>
	<b>Serial#</b>	<b>Appr Hrs</b>	<b>0.10</b>	<b>Appr Labor Amt \$19.50</b>
	<b>Notes</b>			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-26 16:07:02 :: FITTING ON TOILET IS LEAKING The fitting was loose. Tightened the fitting and cleaned up the water.			
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>0.10</b>	<b>Sub Labor Amt \$19.50</b>
	<b>Serial#</b>	<b>Appr Hrs</b>	<b>0.10</b>	<b>Appr Labor Amt \$19.50</b>
	<b>Notes</b>			

### Labor

<b>Line# 3</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-26 16:08:17 :: THE FITTING ON THE WATER PUMP IS LEAKING The cone washer was not sealing on the water pump. Replaced the cone washer. Pressurized water system to test.			
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>0.10</b>	<b>Sub Labor Amt \$19.50</b>
	<b>Serial#</b>	<b>Appr Hrs</b>	<b>0.10</b>	<b>Appr Labor Amt \$19.50</b>
	<b>Notes</b>			

### Labor

<b>Line# 4</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-26 16:08:55 :: ENTRY DOOR IS WARPED Door is warped at the top. Took a block of wood and bent the door away from the frame. Door shuts easily now.			

Model#

Dlr Sub Hrs 0.30

Sub Labor Amt \$58.50

Serial#

Appr Hrs 0.30

Appr Labor Amt \$58.50

Notes

<b>Submitted</b>	Labor Amt	\$117.00
	Parts & Freight	\$0.00
	Total	\$117.00

<b>Approved</b>	Labor Amt	\$117.00
	Parts & Freight	\$0.00
	Total	\$117.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

All repairs described have been inspected and are satisfactory.