



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79784
Promised Date:
20 MAY 26

CUSTOMER WORK ORDER

WO #: 79784

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0529 check WORK

Stock #: 11746
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE GREY WOLF 28RRTS
Chassis #: 4X4TCKD2XTK099988
Serial #: 4X4TCKD2XTK099988
Mileage: 0
Licence:

Invoice #:
Date In: 30 APR 26
Promised: 30 MAY 26
Date Sched:
Completed: 28 MAY 26
Warr. Date:

Job #PDINTT - Internal
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal
COMPLAINT: NO REMOTE FOR THE FIREPLACE

CAUSE: No remote shipped with camper

CORRECTION: Grabbed spare remote from parts and tested. Fireplace operates properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty
COMPLAINT: ALL OF THE CABINET DOORS RUB THERE ARE 3 SETS

CAUSE: Doors installed too close from factory

CORRECTION: Spaced doors out

Labor



Customer #: 1000
BASDEN'S AMERICAN RV,



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	48.75

Subtotal for Job #2: 48.75

Job #3 - Warranty

COMPLAINT: BATHROOM SLIDING DOOR RUBS AND IS SEVERELY SCRATCHED

CAUSE: Door installed too close to the wall and scratched from factory

CORRECTION: Adjusted rail but no wood putty will mask scratches. Remove and replace door

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	78.00
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	78.00

Parts				
Part #	Description	Qty	Price	Total
F100609563	DOOR, PASSAGE 24" X 74" - BRAEMAR E	1.00	60.72	60.72

Subtotal for Job #3: 216.72

Job #4 - Warranty

COMPLAINT: THE BATHROOM MIRROR IS SCRATCH AND THE WOOD AROUND IT IS ASWELL

CAUSE: Damaged from factory

CORRECTION: Remove and replace mirror

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	78.00
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	0.00

Parts				
Part #	Description	Qty	Price	Total
F100705119	DOOR, CABINET 19.5" X 27" CURIO SQUA	1.00	30.23	30.23
30I95480A	MIRROR, 16" X 23-1/2" PLAIN MIRROR P	1.00	8.31	8.31

Other Services			
Code	Description	Qty	Total
FRT	UPS- JOBS 4,7	1.00	44.71

Subtotal for Job #4: 161.25

Job #5 - Warranty

COMPLAINT: THE MAIN SCREEN DOOR LATCH NEEDS ADJUSTED

CAUSE: Latch on door was grabbing screen door handle

CORRECTION: Adjusted latch up

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

Subtotal for Job #5: 39.00

Job #6 - Warranty

COMPLAINT: THE WATER HEATER DOOR IS HARD TO CLOSE

CAUSE: Door frame not properly Adjusted

W/O: 79784
Promised Date: 30 MAY 26



Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: Adjusted door frame. Door latches properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

Subtotal for Job #6: 39.00

Job #7 - Warranty

COMPLAINT: THE CABINET DOOR ABOVE THE BED HAS SCRATCHES

CAUSE: Door scratched from factory

CORRECTION: Remove and replace door

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	0.00

Parts

Part #	Description	Qty	Price	Total
F100713530	DOOR, CABINET, 25-1/4" X 16" E/B SLA	1.00	15.60	15.60

Subtotal for Job #7: 74.10

Parts Total: 114.86
Labour Total: 419.25
Sublet Total: 0.00
Extras Total: 44.71
WORK ORDER TOTAL: 578.82

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 May 2026

W/O: 79784
Promised Date: 30 MAY 26



Customer #: 1000
BASDEN'S AMERICAN RV,

