

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 79887  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 56778 - EMILY ART  
Address: 118 SHADOW VALLEY LN TRENTON, GA

30752

Phone: 256-695-8773

Stock Number: 11698 - 2026 CATALINA 303RKDSLE 5ZT2CAVB1TX036824

VIN: 5ZT2CAVB1TX036824 HIN: SER#: 5ZT2CAVB1TX036824

Mileage: 0 Work Order Comp: 27 MAY 26

Auth. No: Dealer #:

Warr. Date: Work Order Date: 11 MAY 26 Inv #: 430570

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
79887	4	FITTING ON TOILET IS LEAKING The fitting was loose. Tightened the fitting and cleaned up the water.	
79887	3	P TRAP LEAKING UNDER KITCHEN SINK The fitting that connects the p trap to the sink is leaking. Tightened up fitting and filled the sink partially. Cleaned up mess. The sink is no longer leaking.	
79887	5	THE FITTING ON THE WATER PUMP IS LEAKING The cone washer was not sealing on the water pump. Replaced the cone washer. Pressurized water system to test.	
79887	6	ENTRY DOOR IS WARPED Door is warped at the top. Took a block of wood and bent the door away from the frame. Door shuts easily now.	

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
ESC06435	4	CONE WASHER SWIVEL SEAL		1.00	0.26	0.26

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	195.00	19.50

Claim : 79887

\*\*\*\*\*  
Lab Code Job# Description LABOUR Hrs Rate Total  
\*\*\*\*\*

Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	195.00	19.50
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.10	195.00	19.50
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.30	195.00	58.50

Parts Total: 0.26  
Labour Total: 117.00  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 117.26

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_