

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66191

Completed : 21 JAN 22 Customer : 1000 - BASDEN'S AMERICAN RV -
 Licence # : Invoice # :
 Stock No : 11057 Description : 2022 TT RIVERSIDE RV INTREPID 240DD
 Tag : Date In : 27 DEC 21 Mileage : 0
 Author : BH Promised :
 Location : 0130 CHECK WORK Date Sched :
 Serial# : 59CCC3625NL004595 Chassis# : 59CCC3625NL004595
 Warr. Date : Cust PO# :
 Print Date : 21 JAN 22

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
PDIN   Transferred to BAS*66237 on 04 JAN 22 Estimate      I   PDI   PRE-D
       amount was 0.00 PDI - NEW TRAVEL TRAILER
1      COMPLAINT:  THE ENTRANCE DOOR IS MISSING A LOCK      W   49672  RIVER
       CYLINDER
       CORRECTION:  took off old lock and installed new
       lock.
2      COMPLAINT:  THE RIGHT FRONT BASEMENT DOOR IS MISSING W   49672  RIVER
       A LOCK CYLINDER
       CORRECTION:  took off old lock and replaced with new
       lock.
3      COMPLAINT:  THE INSIDE FREEZER BRACKET IS BROKEN      W   49672  RIVER
       CORRECTION:  took out broken bracket and installed
       new bracket.
4      THE SPARE TIRE IS A DIFFERENT SIZE THAN THE REST OF W   49672  RIVER
       THE TIRES.
5      COMPLAINT:  THE RIGHT BEDROOM SLIDE DOOR NEEDS TO BE W   49672  RIVER
       ADJUSTED
       CORRECTION:  took trim down to get to door rollers
       and adjusted door,put trim back in
       place.
6      COMPLAINT:  THE WOOD INSIDE BOTH FRONT BASEMENT      W   49672  RIVER
       DOORS HAS CAME AWAY FROM THE METAL.
       CORRECTION:  sealed wood to metal
7      COMPLAINT:  THE UNION AT THE TOP SIDE REAR OF THE      W   49672  RIVER
       WATER HEATER IS BROKEN
       CORRECTION:  had to get broken union out of water
       heater,replaced with copper union.
8      COMPLAINT:  THE FREEZER WONT LATCH                    W   49672  RIVER
       CORRECTION:  adjusted freezer door.
9      COMPLAINT:  SCREEN DOOR WONT STAY LATCHED TO OUTSIDE W   49672  RIVER
       DOOR WHEN OPENING
       CORRECTION:  adjusted screen door latch.
10     COMPLAINT:  BOTTOM FITTING ON WATER HEATER IS        W   49672  RIVER
       LEAKING
```

Continued on page 2

Work Order : 66191

 Job # Description JOB INFORMATION Type Bill To

CORRECTION: had to remove fitting and it broke
 off, then had to remove broken fitting
 installed new fitting and pex tubing and
 2 clamps and screw on fitting, got all
 together and hot side valve would not
 shut off all the way so took fitting out
 and added a check valve, all is good.

11 OUTSIDE SHOWER IS BROKE AND LEAKING. NEEDS NEW FAUCET W 49672 RIVER

 Job # Part No Description PARTS Bill to Qty Price Total

PDINT	13034	55362 STD BATTERY	I-PDI	0	10.95	0.00
PDINT	24181	-50 RV ANTI-FREEZE	I-PDI	0	4.99	0.00
10	72-0818	1/2" MPT TO 1/2" P	W-49672	1	2.40	2.40
10	681487	1/2" BARB X 1/2 FP	W-49672	1	2.70	2.70
10	677229	1/2" HEX NIPPLE	W-49672	4	6.42	25.68

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

DINTT	Z991	MISC LABOUR CODE (INTE DGH	I-PDI	0.00	130.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH	I-PDI	0.00	130.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH	I-PDI	0.00	130.00	0.00
	1 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.20	130.00	26.00
	2 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.20	130.00	26.00
	3 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.40	130.00	52.00
	4 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.20	130.00	26.00
	5 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.20	130.00	26.00
	6 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.20	130.00	26.00
	7 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.50	130.00	65.00
	8 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.30	130.00	39.00
	9 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.10	130.00	13.00
	10 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	1.00	130.00	130.00
	11 Z990	MISC LABOUR CODE (EXTE DGH	W-49672	0.50	130.00	65.00

 Job # Excode Description EXTRAS bill to Qty Price Total

DINTT	SS	SHOP SUPPLIES	I-PDI	0.00	35.00	0.00
DINTT	LP20	20 LB. LP CYLINDER	I-PDI	0.00	14.00	0.00

 CUSTOMER COMMENTS

PARTS ARRIVED N/C IN BACKROOM 1-17-22...CAM
 BH SENT PREAUTH WAITING TO HEAR BACK

Work Order : 66191

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	49672	30.78	494.00	0.00	0.00	0.00	524.78
	Totals	30.78	494.00	0.00	0.00	0.00	524.78

Claim : 66191

```
*****
WO #      Job #   Description      JOB INFORMATION
*****
66191     7       THE UNION AT THE TOP SIDE REAR OF THE WATER HEATER IS BROKEN
          had to get broken union out of water heater, replaced with copper
          union.
66191     8       THE FREEZER WONT LATCH
          adjusted freezer door.
66191     9       SCREEN DOOR WONT STAY LATCHED TO OUTSIDE DOOR WHEN OPENING
          adjusted screen door latch.
66191    11      OUTSIDE SHOWER IS BROKE AND LEAKING. NEEDS NEW FAUCET
*****
```

```
*****
Part No   Job#   Description      PARTS      Qty      Price      Total
*****
72-0818   10    1/2" MPT TO 1/2" P          1.00     2.40       2.40
69-9014   10    1/2" BARB X 1/2 FP         1.00     2.70       2.70
677229    10    1/2" HEX NIPPLE           4.00     6.42      25.68
*****
```

```
*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990     10    MISC LABOUR CODE (EXTERNAL)      1.00    130.00    130.00
Z990     1     MISC LABOUR CODE (EXTERNAL)      0.20    130.00    26.00
Z990     2     MISC LABOUR CODE (EXTERNAL)      0.20    130.00    26.00
Z990     3     MISC LABOUR CODE (EXTERNAL)      0.40    130.00    52.00
Z990     4     MISC LABOUR CODE (EXTERNAL)      0.20    130.00    26.00
Z990     5     MISC LABOUR CODE (EXTERNAL)      0.20    130.00    26.00
Z990     6     MISC LABOUR CODE (EXTERNAL)      0.20    130.00    26.00
Z990     7     MISC LABOUR CODE (EXTERNAL)      0.50    130.00    65.00
Z990     8     MISC LABOUR CODE (EXTERNAL)      0.30    130.00    39.00
Z990     9     MISC LABOUR CODE (EXTERNAL)      0.10    130.00    13.00
Z990    11    MISC LABOUR CODE (EXTERNAL)      0.50    130.00    65.00
*****
```

Parts Total: 30.78
 Labour Total: 494.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 524.78

Customer Signature: _____

Date: _____