

Pre-Authorization

Pre-Authorization number PA03017271 Reference no: 66214 Status: Approved Approved by flins Approved date 1/5/2022
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGN27N3106023
 600 E Baseline Rd
 Evansville, IN 47725

| Nu mbe r of | Root operation | Description | Sublet | Sub hours | Approved hours | Actual hours | Qty | Base hours | Complaint / Cause / Correction |
|-------------------|-------------------|---------------------|--------|-----------|-------------------|-----------------|-----|---------------|--|
| 1 | 2203314D | Sealant - Roof On | 0.00 | 2.00 | | | 1 | 0.30 | Complaint:PUTTY TAPE IS COMMING OUT OF THE SEAMS Cause:INSTALLED TOO MUCH Correction:cleaned up the putty tape mess from factory and any other spot that needed attention KRV – Unit built in accordance with current manufacturing specifications. |
| 2 | 2300108A | Entrance Door - H | 0.00 | 0.75 | 0.70 | | 1 | 0.20 | Complaint:DOOR FRAME IS DAMAGED FROM THE STEPS Cause:INSTALLED WRONG Correction:touch up and straighten frame and adjusted for steps |
| 3 | 2103408A | Slide Out - Box - I | 0.00 | 0.40 | 0.10 | | 1 | 0.10 | Complaint:SLIDEOUT TRIM IS DAMAGED NEEDS TOUCHED UP Cause:NEED TOUCHED UP Correction:TOUCHED UP ANY SPOTS THAT WAS NEEDED KRV – Labor time approved in accordance with Keystone RV's flat rate manual. |
| | | | | | <u>0.80</u> | | | | |

Pre-Authorization number PA03017271

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company