

Tag Number: _____

Estimate No. 1598
Estimate Date: Jun 10 26



Oxidation RV Repair Service
4516 2nd St NW
Albuquerque, NM 87107
505-417-9386
oxidationrv@gmail.com

Customer: Myers RV Center
12024 Central Ave SE Albuquerque
NM 87123
Forest River
Make: Columbus Model: _____
Year: 25 VIN: 4X4FCMR2096014892

| Estimate | Amount |
|--|---------------------------------|
| Repair stress crack Driverside rear 1st Comp Door | |
| R-I Comp Door | |
| Repair Stress crack | |
| Grind Repair Fiberglass Mat | |
| Kitty Hair Fiberglass | |
| Putty | |
| Prime | |
| Clear Silicone | |
| Paint Base | |
| Clear | |
| Colorsand Buff. | |
| | Paint Mix \$ 250 ⁰⁰ |
| | Waste Disposal 10 ⁰⁰ |
| | Shop Supplies 10 |
| | Labor 616 |
| | Parts |
| | Misc. |
| | Subtotal |
| | Sales Tax |
| | Total \$ 886 ⁰⁰ |

Adjuster Name: _____
Telephone No. _____
Customer Signature: BR

Claim Number: _____
Date: _____