

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66249

Completed : 31 JAN 22 Customer : 49672 - RIVERSIDE RV - 260-499-4578
Licence # : Invoice # :
Stock No : 10662 Description : 2021 TT RIVERSIDE RV INTREPID 280QB
Tag : Date In : 05 JAN 22 Mileage : 0
Author : BH Promised :
Location : 0210 WAITING ON WATDate Sched :
Serial# : 59CCC3627ML004113 Chassis# : 59CCC3627ML004113
Warr. Date : 02 NOV 21 Cust PO# :
Print Date : 02 FEB 22

Job # Description JOB INFORMATION Type Bill To

WINT COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS. E 45238 FUNKH
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA **DE-WINTERIZATION IS NOT
INCLUDED**
CORRECTION: WINTERIZED.
1 COMPLAINT: WATER HEATER BYPASS VALVE LEAKS I SPN SALES
CORRECTION: HOOKED UP HOSE TO CAMPER TO SEE WHERE IT
WAS LEAKING FOUND LEAK AND HOSE FOR SINK
BLEW, TURNED OFF WATER AND FOUND HOSE AND
CLEANED UP ALL THE WATER. NEED NEW
KITCHEN FAUCET. CUT HOT AND COLD LINES
OFF OF VALVE, CUT BOTH CLAMS OFF AND PUT
NEW CLAMPS ON, FILLED WATER HEATER AND
CHECKED FOR LEAKS ALL IS GOOD.
2 COMPLAINT: KITCHEN FAUCET HOSE BLEW OFF, CONNECTION W 49672 RIVER
IS BAD.
CORRECTION: TURNED WATER ON AND FAUCET CONNECTION
BLEW OFF, TURNED WATER OFF AND CLEANED UP
WATER, TOOK OUT FAUCET, WAITING ON
FAUCET, CAPPED LINES.
3 COMPLAINT: WATER PUMP NOT PULLING WATER FROM THE W 49672 RIVER
TANK
CORRECTION: TOOK PICTURES OF PUMP AND TOOK PUMP
OUT, HAD HARD TIME GETTING SCREWS OUT
BECAUSE IT WAS AGAINST WALL, NO
ROOM, WIRED NEW PUMP AND INSTALLED, WORKS
FINE.

Job # Part No Description PARTS Bill to Qty Price Total

WINT 24181 -50 RV ANTI-FREEZE E-45238 2 4.49 8.98
2 C01292791 1/2" PVC RED HOSE HI-PRESSU W-49672 2 0.33 0.66

Continued on page 2

Work Order : 66249

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
2 C01292790 1/2" BLUE PVC HIGH PRESSURE W-49672 2 0.33 0.66
3 10-7150 CONE WASHER SWIVEL W-49672 1 0.24 0.24
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
INTER Z990 WINTERIZE UNIT DGH E-45238 0.06 130.00 7.80
INTER Z990 WINTERIZE UNIT DGH E-45238 0.60 130.00 78.00
INTER Z990 WINTERIZE UNIT DGH E-45238 0.34 130.00 44.20
1 Z990 MISC LABOUR CODE (EXTE DGH I-SPN 0.00 25.00 0.00
1 Z990 MISC LABOUR CODE (EXTE DGH I-SPN 1.00 25.00 25.00
1 Z990 MISC LABOUR CODE (EXTE DGH I-SPN 0.00 25.00 0.00
1 Z990 MISC LABOUR CODE (EXTE DGH I-SPN 0.00 25.00 0.00
2 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
2 Z990 MISC LABOUR CODE (EXTE DGH W-49672 0.50 150.00 75.00
2 Z990 MISC LABOUR CODE (EXTE DGH W-49672 0.00 150.00 0.00
2 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
3 Z990 MISC LABOUR CODE (EXTE DGH W-49672 0.00 150.00 0.00
3 Z990 MISC LABOUR CODE (EXTE DGH W-49672 0.50 150.00 75.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
INTER SS SHOP SUPPLIES E-45238 1.00 9.70 9.70
*****
```

CUSTOMER COMMENTS

```
*****
WATER PUMP ARRIVED 1-24-22 N/C...CAM (PUT ON SHELF)
DO NOT CLOSE RO UNTILL PARTS SHOW!!!!!!
WATER PUMP ORDERED. 1-14-22
FAUCET ARRIVED N/C - IN BACK ROOM. 1-14-22
WHEN PUMP SHOWS WE NEED TO PUT ON PARTS SHELF
BH GOT APPROVEL FOR THE WATER PUMP AND GAVE MATT THE PARTS ORDER
SHEET
FAUCET ORDERED VIA EMAIL 1-7-22...CAM
BH GOT APPROVEL FOR 66238
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
E 45238 8.98 130.00 0.00 9.70 1.31 149.99
I SPN 0.00 25.00 0.00 0.00 0.00 25.00
W 49672 1.56 150.00 0.00 0.00 0.00 151.56
Totals 10.54 305.00 0.00 9.70 1.31 326.55
*****
```

Continued on page 3

Work Order : 66249