



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26977



WO #: 26977

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11297

Stock Desc: 2026 TT KEYSTONE BULLET 245RKS

Model: 245RKS

Serial #: 4YDTBLL22TD431682

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 10 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: the 2nd drawer down from from top to the left of entry is damaged and rough

CAUSE: noted on daf
wood damaged when built

CORRECTION: remove drawer and guides, replace with new drawer and reinstall guides then test drawer
labor .60

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: cabinetry above 2nd drawer in kitchen is damaged

CAUSE: wood is rough and looks damaged on cabinetry door
noted on daf

CORRECTION: remove the damaged cabinetry stile and replace with new
labor .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: top cabinet door 1st on left at entry door has a defective area

CAUSE: damaged at factory instll
noted on daf

CORRECTION: smooth area on cabinet door, fill, color blend area
labor .40

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: 2nd cabinet door at entry is cracked

CAUSE: noted on daf

CORRECTION: remove damaged cabinet door and the hardware, replace cabinet door with new one and
reinstall hardware
labor .50

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



W/O: 26977

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: left side of slide out fascia is scratched and paint faded in spots

CAUSE: noted on daf

CORRECTION: fill, color and blend areas
labor .40

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: bathroom door from the living area has scratched paint in several areas

CAUSE: noted on daf

CORRECTION: fill, color and blend areas
labor .40

Subtotal for Job #6: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 10 Apr 2026

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,