

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Authorized
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2707270
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	5ZT2TRNB7TB526454
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	048 / 048B
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	TRT235RK
BOBBI BARRERA		<b>DEALER RO #</b>	73533
11220 DEER LODGE PLACE SE		<b>CLAIM START DATE</b>	06/11/2026
Albuquerque, NM 87123		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	06/11/2026	<b>WARRANTY EXPIRATION DATE</b>	06/11/2027

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-06-11 14:24:09 :: Complaint: Decal is peeling at rear entry door Cause: Defective decal Correction: Replace decal			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>0.50</b>	<b>Sub Labor Amt</b>	<b>\$95.00</b>
<b>Serial#</b>	<b>Appr Hrs</b>	<b>0.30</b>	<b>Appr Labor Amt</b>	<b>\$57.00</b>
	<b>Notes</b>			
	The pictures provided on this repair line do not show the problem described in the Complaint, Cause, & Correction. The picture is not clear or is too far away from the item to see the problem. Please attach pictures that show the problem.			
	I've added a zoomed in picture with the defect highlighted.			
	Excessive labor requested to remove damaged graphic from glass entry door and replace. Reduced to a reasonable amount.			
	NO VCB			

<b>Submitted</b>	Labor Amt	\$95.00	<b>Approved</b>	Labor Amt	\$57.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$95.00		Total	\$57.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
All repairs described have been inspected and are satisfactory.