



Warranty Claim Detail

R.O. Number 73383
Job 1

COMPLAINT INFORMATION	
Flat Rate Code	0282
Description	Cabinet-Newmar, Combo Desk/Dinette
Occurrences	1
Requested Hours	1.00
Authorized Hours	1.00
Fault Code	21-Gaps
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.00

CUSTOMER COMPLAINT
COMMENT ENTERED ON 06/03/2026 AT 12:40 PM BY DEALER Dinette table fascia has pulled off
AUTHORIZATION NOTES
DEALER CORRECTION
COMMENT ENTERED ON 06/03/2026 AT 12:40 PM BY DEALER Found table fascia detached. Puled unit up and run slide out to gain work space, dete rmine proper placement for the board, grab air staple gun and determine correct stapl es. Install fascia in factory location and added additional staples to gain strength at attachment points.

GENERAL INFORMATION	
Status	Paid
Date In	05/19/2026
Submit Date	06/03/2026
Authorization	No 06/04/2026
Work Complete	Yes 06/04/2026
Payment	Yes 06/10/2026

TOTALS	Requested	Authorized
Labor	185.00	185.00
Sublet	.00	.00
Parts	4.63	4.63
Freight	.00	.00
Adjustments	.00	.00
TOTAL	191.02	191.02
TOTAL PAID		191.02

