

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66382
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11176 - 2022 RETRO 171DRD 59CCC451XNL005014
VIN: 59CCC451XNL005014 HIN: SER#: 59CCC451XNL005014
Mileage: 0 Work Order Comp: 28 FEB 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 25 JAN 22 Inv #: 373636

WO # Job # Description JOB INFORMATION

66382 2 ENTRY DOOR HANDLE ONE OF THE HOLES FOR THE MOUNTING SCREW BROKE
NEEDS REPLACED
door handle is broken and needs replaced. mounting bracket is
broken
removed old handle. installed new handle

66382 1 BEDROOM WALL IA PUSHING OUT AND SEAM TAPE IS BUNCHED UP
wall in bedroom is pushing out and seam tape is bunched up in the
middle
secured wall with brad nails. took a piece of a trim to match and
added to cover seam tape.

66382 3 SEALER AROUND WINDOW ON DRIVERS SIDE
sealer around window on drivers side
removed with mineral spirits

66382 4 SCREEN DOOR LATCH NEEDS ADJUSTED
screen door latch isnt catching door
moved latch to catch main door

66382 5 ENTRY DOOR IS HITTING THE FRAME
entry door is hitting the frame at the top left corner and is
hitting latch plate.
took a hammer and moved latch plate over from door. took a block
of wood and a hammer and pushed door frame "in" away from door.

Claim : 66382

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
66382      6      CORNER TRIM UNDER RADIO IS DAMAGED AND NEEDS PUTTY
               corner is damaged.
               took putty and stain and applied to damaged area as needed.

66382      7      THE BATHROOM DOOR HITS THE DOOR FRAME
               door is hitting plastic frame.
               took a screw and painted it black to match the trim. installed
               screw to hold frame in place

```

```

*****
Part No    Job#   Description      PARTS
*****
CPGTTL-43610-  2   LOCK ASSEMBLY-BLAC
                               Qty      Price      Total
                               1.00      22.51      22.51

```

```

*****
Lab Code   Job#   Description      LABOUR
*****
Z990       2      MISC LABOUR CODE (EXTERNAL)
Z990       1      MISC LABOUR CODE (EXTERNAL)
Z990       1      MISC LABOUR CODE (EXTERNAL)
Z990       3      MISC LABOUR CODE (EXTERNAL)
Z990       4      MISC LABOUR CODE (EXTERNAL)
Z990       5      MISC LABOUR CODE (EXTERNAL)
Z990       6      MISC LABOUR CODE (EXTERNAL)
Z990       7      MISC LABOUR CODE (EXTERNAL)
                               Hrs      Rate      Total
                               0.20     150.00     30.00
                               0.00     150.00      0.00
                               0.20     150.00     30.00
                               0.20     150.00     30.00
                               0.20     150.00     30.00
                               0.20     150.00     30.00
                               0.20     150.00     30.00
                               0.20     150.00     30.00

```

```

Parts Total:      22.51
Labour Total:     210.00
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>> Claim Total:      232.51

```

Customer Signature: _____

Date: _____