



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73328
Promised Date:
07 MAY 26



WO #: 73328

Customer Name: 55266 - MILKS,
CHARLES HARLAND JR

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 2024 VENTANA 4369
Serial#: 416351
Chassis#: 4UZFCHFE4PCUS0691
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 07 MAY 26
Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES ENTRY DOOR WINDOW FOGGED

CAUSE: DEFECTIVE WINDOW

CORRECTION: CUSTOMER CALLED NEWMAR

Please have the dealer reference case# 01087725 when they submit for warranty approval.

Thank you,
Jeff Johnson

Customer #: 55266
MILKS, CHARLES
HARLAND JR

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 07 May 2026

