



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27154



WO #: 27154

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11309  
Stock Desc: 2026 TT FOREST RIVER  
ROCKWOOD ULTRA 2608BS  
Model: 2608BS  
Serial #: 4X4TRLB20TZ201989  
Chassis #:  
Mileage: 0  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date:  
Date In: 13 MAY 26  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date:

**Job #1 - Warranty**

COMPLAINT: KITCHEN DRAWER FRONT AT SINK IS CRACKED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND DAMAGED FRONT ON DRAWER AND REPLACE WITH NEW ONE  
LABOR .40

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: CHIP IN THE PANTRY DOOR TO THE LEFT OF ENTRY

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .10

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: BATHROOM DOOR HANDLE HAS PAINT FADED

CAUSE: NOTED ON DAF  
PAINT DEFECT

CORRECTION: REPLACE DOOR HANDLE  
LABOR .20

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: BATTEN IN KITCHEN NOT ATTACHED AND LOOSE

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BACK IN CORRECT PLACE  
LABOR .20

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #4: 0.00

W/O: 27154

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
-----

X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967  
-----

Customer Signature : \_\_\_\_\_

Date: 13 May 2026



Customer Work Order

Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

