

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2699691
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVRBXTB941728
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT26DBS
PHILLIP VANDER KRAATS		DEALER RO #	73486
726 TRAMWAY VISTA DR NE APT 12		CLAIM START DATE	06/04/2026
Albuquerque, NM 87122		CLAIM END DATE	06/05/2026
USA			
Retail Date of Purchase	03/28/2026	WARRANTY EXPIRATION DATE	03/28/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-06-04 18:30:41 :: Complaint: Center lights are inop Cause: The wire supplying power to the lights was tied to the slide switch and the fuse was blowing. Correction: Removed each light, starting from the furthest light from the breaker panel. Removed light and tested. All the lights were working correctly. Pulled the power converter and checked the wires, all seemed ok. Pulled the switch panel and traced wires and noticed the wires were tied into the switches for the slide. Moved the wire over to the light switches and it started working. Replace blown fuse.			
Model#	Dlr Sub Hrs	2.85	Sub Labor Amt	\$541.50
Serial#	Appr Hrs	2.00	Appr Labor Amt	\$380.00
	Notes			
	Excessive labor requested. Reduced to a reasonable amount.			

Part

Line# 1	Item #	Description		
	USERPART	ATC 15 Fuse		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.23
	Appr Qty	1.00	Appr Dlr Price	\$0.23
			Sub Freight	\$0.00
			Appr Freight	\$0.00
	Notes			

Submitted	Labor Amt	\$541.50	Approved	Labor Amt	\$380.00
	Parts & Freight	\$0.23		Parts & Freight	\$0.23
	Total	\$541.73		Total	\$380.23

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	