

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2609525
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	5ZT2TRFC3SB525758
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	048 / 048B
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	TRT170RS
BOBBIE HARTLINE		<b>DEALER RO #</b>	73027
1108 JACOBS DR NE		<b>CLAIM START DATE</b>	03/13/2026
Rio Rancho, NM 87144		<b>CLAIM END DATE</b>	06/10/2026
USA			
<b>Retail Date of Purchase</b>	05/22/2025	<b>WARRANTY EXPIRATION DATE</b>	05/22/2026

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>
	70-223-01-11-002736	Range Oven - complete - Appliances/Range, Oven (Furrion/Greystone)/Replace/ Electrical

#### Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-03-13 17:06:25 :: Complaint: Customer states stove top is flaking Cause: Defective top Correction: Remove and replace top Additional Note : stephanie@dealer-advisors.com, 2026-04-23 10:09:31 :: Just a note that we were able to find the part available now, so this will not need to be the entire range. We can just replace the part.

<b>Model#</b>	FGR17G3MA2B-BG	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$190.00
<b>Serial#</b>	10001784875062400199	<b>Appr Hrs</b>	0.70	<b>Appr Labor Amt</b>	\$133.00

#### Notes

Back on dealer side to update time and parts. AK  
 We tried to order just the grate, and it is not available unless we do the entire unit.  
 Here is a part number from the manual for the stamped grate: 2021124335. AK  
 Yes, we did try to order that part, and it wasn't available. Our service manager is going to try again, or at least try to find out why it is not available and I will update again once I know.  
 Excessive amount requested. Authorized for .70 to R/R stove top area that is flaking off.  
 Approved per dealers' description. This authorization is pending ALL requirements of repair code have been met. NVCB. AK

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>
	F100308683	STAMPED GRATE, FOR RANGE F1S17L02A-BL/C-F1S17L03A-BL, (FURRIION C-F1S17L02A-001), 2023045674, 2021124335
	<b>Model #</b>	<b>Serial #</b>
	<b>Sub Qty</b>	<b>Sub Dlr Price</b>
	<b>Appr Qty</b>	<b>Appr Dlr Price</b>
		<b>Part tag</b>
		<b>Sub Freight</b>
		<b>Appr Freight</b>

#### Notes

<b>Submitted</b>	<b>Labor Amt</b>	\$190.00	<b>Approved</b>	<b>Labor Amt</b>	\$133.00
	<b>Parts &amp; Freight</b>	\$148.71		<b>Parts &amp; Freight</b>	\$148.71
	<b>Total</b>	\$338.71		<b>Total</b>	\$281.71

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_  
 I certify that I have performed these repairs consistent with Forest

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_  
 All repairs described have been inspected and are satisfactory.

