

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 66399  
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725  
Phone:  
Stock Number: 11197 - 2022 RETRO 171DRD 59CCC4515NL005115  
VIN: 59CCC4515NL005115 HIN: SER#: 59CCC4515NL005115  
Mileage: 0 Work Order Comp: 14 APR 22  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 27 JAN 22 Inv #: 375417

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
66399 1 FRESH TANK FILL LINE RUNS UPWARD NEED TO REROUTE LINE  
FILL HOSE NEEDS MOVED SO IT HAS A "SLOPE DOWN INTI THE TANK  
VERY DIFFICULT TO ACCESS HOSE CLAMP. REMOVED HOSE CLAMP. RE  
ROUTED HOSE. CUT TO LENGTH. SECURED HOSE WITH CLAMP. FILLED TANK  
66399 3 CORNER OF SHOWER NEEDS SEALED  
corner of shower needs sealed with silicone  
sealed with silicone  
66399 4 SEAM TAPE IN BATHROOM IS COMING OFF  
seam tape was coming off.  
applied adhesive to seam tape.  
66399 5 WALL IN BEDROOM IS PUSHING OUT ON THE DRIVERS SIDE  
WALL IS PUSHING OUT  
SECURED WITH STAPLES AND FILLED HOLES WITH PUTTY  
66399 6 WALL IN BEDROOM ON PASSENGER SIDE IS PUSHING OUT  
WALL PUSHING OUT  
SECURED WITH BRAD NAILS AND FILLED WITH PUTTY  
66399 7 CABINET ABOVE SINK. TRIM NEEDS SECURED  
trim was loose inside the cabinet  
secured trim with brad nails.  
66399 8 DENT IN A HUBCAP ON THE OFF DOOR SIDE

Claim : 66399

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*

66399      9      PASSANGER SIDE BRAKE LIGHT NOT WORKING  
 brake light isnt working. removed cover for 7 way junction box.  
 tested each lead for lights. all leads have power. traced wires  
 to the back. tested each wire and all have power. removed light  
 from the camper to test light. noticed the wire was not secure to  
 the light.  
 cut wire and re crimped to light. light is now working. installed  
 cover plate for the 7way. installed light. sealed light with  
 silicone.

\*\*\*\*\*  
 Lab Code   Job#   Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*

|      |   |                             |  |      |        |        |
|------|---|-----------------------------|--|------|--------|--------|
| Z990 | 1 | MISC LABOUR CODE (EXTERNAL) |  | 0.50 | 150.00 | 75.00  |
| Z990 | 3 | MISC LABOUR CODE (EXTERNAL) |  | 0.10 | 150.00 | 15.00  |
| Z990 | 3 | MISC LABOUR CODE (EXTERNAL) |  | 0.10 | 150.00 | 15.00  |
| Z990 | 4 | MISC LABOUR CODE (EXTERNAL) |  | 0.20 | 150.00 | 30.00  |
| Z990 | 4 | MISC LABOUR CODE (EXTERNAL) |  | 0.00 | 150.00 | 0.00   |
| Z990 | 5 | MISC LABOUR CODE (EXTERNAL) |  | 0.00 | 150.00 | 0.00   |
| Z990 | 5 | MISC LABOUR CODE (EXTERNAL) |  | 0.20 | 150.00 | 30.00  |
| Z990 | 6 | MISC LABOUR CODE (EXTERNAL) |  | 0.20 | 150.00 | 30.00  |
| Z990 | 7 | MISC LABOUR CODE (EXTERNAL) |  | 0.10 | 150.00 | 15.00  |
| Z990 | 8 | MISC LABOUR CODE (EXTERNAL) |  | 0.10 | 150.00 | 15.00  |
| Z990 | 9 | MISC LABOUR CODE (EXTERNAL) |  | 0.70 | 150.00 | 105.00 |

Parts Total:      0.00  
 Labour Total:      330.00  
 Sublet Total:      0.00  
 Extras Total:      0.00

>>>> Claim Total:      330.00

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_