



P.O. Box 2000 | Goshen, IN | 46527

Dealer Acceptance Form (DAF)

Customer Service
Phone : (866) 425-4369

Dealership: Link Ford & RV Minong LLC (715) 466-2222

Origin : Indiana

VIN: TE760534

Brand: Avalanche

Model: AV366LS26

"SUBJECT TO FURTHER INSPECTION" DOES NOT APPLY TO TRANSPORTATION DAMAGE!

- DAF is to document possible damage and missing equipment, not normal warranty defects.
- While the driver is present, list the specific location of any of the below questions answered "YES". Keystone will make the determination if the issue is related to the driver transportation.

Keystone shipped units:

- Dealers-No need to e-mail/fax the DAF, the transport driver is required to return the original to Keystone/Dutchmen/CrossRoads

Driver Pick-up (DPU):

- Obvious exterior damage(s) should be reported to the Shipping Department at the time of factory picked-up
- Within 24 hours of receiving the unit at the dealer location, complete the DAF and e-mail to daf@keystonerv.com

Exterior	Yes	No	Location
Evidence of impact/drag on walls/wall components/caps/graphics/paint			
Evidence of impact/drag to rubber roof, roof components or awning			
Evidence of impact/damage/road debris to axles/suspension/underbelly			

Interior	Yes	No	Location
Obvious torn/cut/punctured/stained furniture			
Obvious dinged/dented/scratched TV/Appliance doors/face's/trims			
Obvious torn/cut/punctured/stained carpet/Linoleum			
Obvious dinged/dented/scratched doors/cabinet front's			
Equipment listed on Invoice is on the unit			
Missing items/equipment outside/inside			

Comments:

- Fridge not of adjustment
- Furnace heats up & cools down but doesn't shut off.
- Shower sliding door doesn't move freely.

Dealer Rep Signature <u>Bonnie Seeman</u>	Printed <u>Bonnie Seeman</u>	Date <u>05/06/2026</u>
Driver Signature _____	Printed _____	Date ____/____/____

4YDFAVT22TE760534



Original - Keystone

Yellow - Dealer