

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 66467  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 46875 - CHUBBY CHOW FACTORY LLC  
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 11002 - 2022 SPRINGDALE 260BH 4YDTSGL2XN3106679

VIN: 4YDTSGL2XN3106679 HIN:

SER#: 4YDTSGL2XN3106679

Mileage: 0

Work Order Comp: 14 FEB 22

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 07 FEB 22

Inv #: 372905

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
66467 2 THE JACK HANDLE IS MISSING. THIS WAS NOTED ON DELIVERY.  
THE JACK HANDLE IS MISSING. THIS WAS NOTED AT DELIVERY.  
Replaced missing jack crank handle.  
  
66467 3 THE SPRAY PORT HOSE IS MISSING.  
THE SPRAY PORT HOSE IS MISSING.  
Place new spray port hose in storage compartment.  
  
66467 4 THE WATER HEATER IS NOT WORKING ON LP  
THE WATER HEATER IS NOT WORKING ON LP.  
Tried to light water heater on LP thru 5 cycles. Furnace next to  
runnig fine. Removed igniter and burner tube to check for  
obstructions. Burner tube ok. Igniter tips too close and not  
giving a good spark. Opened up gap on igniter. Remounted all  
parts. Checked operation again. Water heater ignited on first  
try. Burning OK.

\*\*\*\*\*  
Part No Job# Description PARTS Qty Price Total  
\*\*\*\*\*  
102885 2 JACK - CRANK HANDL 1.00 15.04 15.04  
201444 3 BLUE COILED HOSE W 1.00 17.48 17.48

\*\*\*\*\*  
Lab Code Job# Description LABOUR Hrs Rate Total  
\*\*\*\*\*  
Z990 2 MISCELLANEOUS REPAIR 0.10 150.00 15.00

Claim : 66467

```

*****
Lab Code Job# Description LABOUR Hrs Rate Total
*****
Z990 3 MISCELLANEOUS REPAIR 0.10 150.00 15.00
Z990 4 MISCELLANEOUS REPAIR 0.20 150.00 30.00

Parts Total: 32.52
Labour Total: 60.00
Sublet Total: 0.00
Extras Total: 0.00

>>>>> Claim Total: 92.52

```

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_