



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$301.94

RO# : 40825 Tag# : S11L0077

Check-in: Fri May 29, 2026 | 2:13 PM
Ready for Pickup: Fri Jun 5, 2026 | 12:11 PM
Promise Time: Wed Jun 3, 2026 | 6:00 PM

Customer
Michael Klingenberg
1240954
+1 - (715) 316 - 2492
wsp6606@hotmail.com
208 Piehl Ct
Edgar, WI 54426

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2025 JAYCO 40LOFT
JAYFLIGHT BUNGALOW
1UJBC0BV6S11L0077
2 Mi In
Sold Date: 05/13/2025
Stock #: 25-13

Service Advisor
KEVIN GOODIEL
goodielk

A. SC	SERVICE CALL W6548 HWY 77, MINONG 54859	Warranty Pay	\$165.00
-------	---	--------------	----------

Job added by KEVIN GOODIEL on Fri May 29, 2026 | 2:13 PM

Op.1 SC -SERVICE CALL

Labor Sale: \$165.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.85	0	0	\$0.00	\$0.00

1. SERVICE CALL

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$165.00	\$0.00	\$0.00	\$0.00

B. MISCELLANEOUS	CUSTOMER STATES THE VERY BACK WINDOW THERMAL PAIN, IT IS FOGGING UP AND THE SEAL IS BROKEN	Warranty Pay	\$0.00
------------------	--	--------------	--------

Job added by KEVIN GOODIEL on Fri May 29, 2026 | 2:13 PM

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.2	0	0	\$0.00	\$0.00

1. Window is clear at this moment and I do not see any broken seals on it. see if customer can take pictures when it is fogged up, might have something to do with condensation when the air conditioning is running. I took pictures of the window I also checked every window and all other windows look good





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$301.94

RO# : 40825 Tag# : S11L0077

Check-in: Fri May 29, 2026 | 2:13 PM
 Ready for Pickup: Fri Jun 5, 2026 | 12:11 PM
 Promise Time: Wed Jun 3, 2026 | 6:00 PM

Customer Michael Klingenberg 1240954 +1 - (715) 316 - 2492	Billing-Customer Same as Customer	Vehicle 2025 JAYCO 40LOFT JAYFLIGHT BUNGALOW 1UJBC0BV6S11L0077	Service Advisor KEVIN GOODIEL goodielk
--	---	--	---

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

C. MISCELLANEOUS	CUSTOMER STATES THE SEAL ON THE TOILET WILL NOT HOLD WATER	Warranty Pay	\$136.94
-------------------------	---	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri May 29, 2026 | 2:13 PM

1. Bad seal in toilet bowl, needs a new seal requesting .50

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.33	0	0	\$0.00	\$0.00

1. the toilet bowl is not holding water and goes empty within 30 seconds replaced seal and tested toilet is holding water now

Parts

Parts Total Sale Amount \$54.44

Parts Total Cost Amount \$41.88

Name	Quantity	Unit Price	Sale Price	Cost Price
SE311658 - SEAL	1	\$54.44	\$54.44	\$41.88

Total Labor Sale \$82.50	Total Labor Cost \$0.00	Total Parts Sale \$54.44	Total Parts Cost \$41.88
------------------------------------	-----------------------------------	------------------------------------	------------------------------------

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$301.94

RO# : 40825 Tag# : S11L0077

Check-in: Fri May 29, 2026 | 2:13 PM
 Ready for Pickup: Fri Jun 5, 2026 | 12:11 PM
 Promise Time: Wed Jun 3, 2026 | 6:00 PM

Customer
 Michael Klingenberg
 1240954
 +1 - (715) 316 - 2492

Billing-Customer
 Same as Customer

Vehicle
 2025 JAYCO 40LOFT
 JAYFLIGHT BUNGALOW
 1UJBC0BV6S11L0077

Service Advisor
 KEVIN GOODIEL
 goodielk

Category	Sale	Cost
Labor	\$247.50	\$0.00
Parts	\$54.44	\$41.88
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$301.94	\$41.88

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	SC	Wed Jun 3, 2026	12:40 PM	1:14 PM	0.56 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 3, 2026	1:14 PM	1:26 PM	0.20 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Wed Jun 3, 2026	1:26 PM	1:46 PM	0.33 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
A	SC	Wed Jun 3, 2026	1:59 PM	2:16 PM	0.29 hrs	W	boiem	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$301.94

RO# : 40825 Tag# : S11L0077

Check-in: Fri May 29, 2026 | 2:13 PM
Ready for Pickup: Fri Jun 5, 2026 | 12:11 PM
Promise Time: Wed Jun 3, 2026 | 6:00 PM

Customer
Michael Klingenberg
1240954
+1 - (715) 316 - 2492

Billing-Customer
Same as Customer

Vehicle
2025 JAYCO 40LOFT
JAYFLIGHT BUNGALOW
1UJBC0BV6S11L0077

Service Advisor
KEVIN GOODIEL
goodielk

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40825	LINK RV	\$301.94
57200	40825	LINK RV	-\$247.50
67200	40825	LINK RV	\$0.00
14400	boiem	LINK RV	\$0.00
54200	40825	LINK RV	-\$54.44
64000	40825	LINK RV	\$41.88
14000	40825	LINK RV	-\$41.88

