

Dealership: Tri-AM RV Center of East TN 423-235-1167

Origin : Indiana

VIN: TD431682

Brand: Bullet

Model: BL245RKS26

"SUBJECT TO FURTHER INSPECTION" DOES NOT APPLY TO TRANSPORTATION DAMAGE!

- DAF is to document possible damage and missing equipment, not normal warranty defects.
- While the driver is present, list the specific location of any of the below questions answered "YES". Keystone will make the determination if the issue is related to the driver transportation.

Keystone shipped units:

- Dealers-No need to e-mail/fax the DAF, the transport driver is required to return the original to Keystone/Dutchmen/CrossRoads

Driver Pick-up (DPU):

- Obvious exterior damage(s) should be reported to the Shipping Department at the time of factory picked-up
- Within 24 hours of receiving the unit at the dealer location, complete the DAF and e-mail to daf@keystonerv.com

Exterior	Yes	No	Location
Evidence of impact/drag on walls/wall components/caps/graphics/paint			
Evidence of impact/drag to rubber roof, roof components or awning			
Evidence of impact/damage/road debris to axles/suspension/underbelly			

Interior	Yes	No	Location
Obvious torn/cut/punctured/stained furniture			
Obvious dinged/dented/scratched TV/Appliance doors/face's/trims			
Obvious torn/cut/punctured/stained carpet/Linoleum			
Obvious dinged/dented/scratched doors/cabinet front's	X		① 2nd drawer @ Entry to @ damaged ② cabinetry above 2nd drawer damaged ③ Top cabinet door 1st on @ Entry defective Area ④ 2nd cabinet door Entry cracked
Equipment listed on Invoice is on the unit			
Missing items/equipment outside/inside			

Comments: ⑤ Side Slideout fascia scratched ⑥ Bathroom door from living Area scratched paint diff. places

Dealer Rep Signature	<i>Stephanie Davis</i>	Printed	Stephanie Davis	Date	4/3/26
Driver Signature	<i>Kelly Rowe</i>	Printed	Kelly Rowe	Date	4/3/26

4YDTBLL22TD431682

