

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66538
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV
Customer: 52247 - JANE S. WATHEN
Address: 3905 NEEDLE LEAF PT EVANSVILLE, IN

47715

Phone: 812-480-4350

Stock Number: 11069 - 2022 RETRO 190BH 59CCC4613NL004687

VIN: 59CCC4613NL004687 HIN:

SER#: 59CCC4613NL004687

Mileage: 0

Work Order Comp: 23 MAR 22

Auth. No:

Dealer #:

Warr. Date: 31 JAN 22

Work Order Date: 18 FEB 22

Inv #: 374414

WO # Job # Description JOB INFORMATION

66538 1 INSTALL NEW WATER HEATER BECUASE THE OLD WATER HEATER WAS
INSTALL INCORRECTLY WE WILL HAVE TO LIFT THE BED FRAME 4 IN TO
MAKE FIT
INSTALL WATER HEATER. NEED TO RAISE BED FRAME FOR NEWWATER
HEATER TO FIT CORRECTY.
REMOVED BED PAD, WOOD ACCESS PANEL, ALL TRIM, REMOVED BRACE
RUNNING OVER WATER HEATER, TURNED OFF BREAKER, CUT WIRES TO
WATER HEATER. REMOVED PLASTIC BAND THAT HOLDS WATER HEATER IN
PLACE. REMOVED PVC PIPE THAT THE PRESSURE RELEIF VALVE HAS
INSTALLED ON IT. CUT WATER LINES. REMOVED OLD WATER HEATER.
TOOK NEW WATER HEATER AND SET IT INSIDE CAMPER. HOOKED UP WATER
LINES. ADDED A UNION TO THE COLD WATER LINE SO IT COULD REACH.
CUT ,CLEANED AND GLUED NEW PVC TO HIGH PRESSURE RELEIF VALVE.
NEW WATER HEATER HAS A CORD. INSTALLED A OUTLET FOR PLUG
IN.SECURED TO FLOOR WITH PLASTIC BAND. TURNED BREAKER ON AND
WATER HEATER ON. TURNED ON WATER. UNION ON COLD LINE LEAKED.
REPLACED UNION. WATER HEATER IS WORKING. NO LEAKS WINTERIZED
UNIT AND WATR HEATER SINCE YOU CAN'T DRAIN IT. TOOK 2X4'S AND
BUILT THE BEDFRAME UP S IT WOULD CLEAR WATER HEATER. SECURED
FRAME WITH SCREWS AND LIQUID NAILS. ADDED ADDITIONAL SUPPORT TO
THE ENTIRE FRAME TO HELP SUPPORT ITSELF.HAD TO CUT A LONGER
PIECE OF TRIMM AND BUILD A BACKING PLATE FOR THE TRIM IN FRONT
OF THE BUNK SI IT SITS FLUSH. INSTALLED WOOD PANEL WITH SCREWS
AND STAPLES. INSTALLED BED. CUT NEW TRIM PIECES. SECURED WITH
STAPLES. CLEANED UP MESS. PARKED CAMPER

Claim : 66538

```

*****
WO #      Job #   Description          JOB INFORMATION
*****

```

```

*****
Part No   Job#   Description          PARTS
*****
RVDS811   1   S811 WHITE DUAL OU
88-8302   1   BARB UNION
88-8309   1   BARB ELBOW 1/2 X 1

```

Part No	Job#	Description	Qty	Price	Total
RVDS811	1	S811 WHITE DUAL OU	1.00	7.79	7.79
88-8302	1	BARB UNION	2.00	0.52	1.04
88-8309	1	BARB ELBOW 1/2 X 1	1.00	0.86	0.86

```

*****
Lab Code  Job#   Description          LABOUR
*****
Z990      1   MISC LABOUR CODE (EXTERNAL)
Z990      1   MISC LABOUR CODE (EXTERNAL)
Z990      1   MISC LABOUR CODE (EXTERNAL)

```

Lab Code	Job#	Description	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)	1.00	150.00	150.00
Z990	1	MISC LABOUR CODE (EXTERNAL)	3.20	150.00	480.00
Z990	1	MISC LABOUR CODE (EXTERNAL)	1.80	150.00	270.00

```

*****
Excode    Job#   Description          EXTRAS
*****
PARTS     1   PIPE, FITTINGS, AND GLUE

```

Excode	Job#	Description	Qty	Price	Total
PARTS	1	PIPE, FITTINGS, AND GLUE	1.00	24.43	24.43

```

Parts Total:      9.69
Labour Total:     900.00
Sublet Total:     0.00
Extras Total:     24.43

```

>>>> Claim Total: 934.12

Customer Signature: _____

Date: _____