

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66540
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 10732 - 2022 SPRINGDALE 295BH 4YDTSGN28N3106774
VIN: 4YDTSGN28N3106774 HIN: SER#: 4YDTSGN28N3106774
Mileage: 0
Auth. No: Work Order Comp: 28 FEB 22
Warr. Date: Dealer #: 1194
Work Order Date: 18 FEB 22 Inv #: 373301

WO # Job # Description JOB INFORMATION

66540 2 THE FRONT STABILIZER JACKS ARE NOT WORKING AT ALL
JACK NOT WORKING
CHECKED WIRES, SWITCH AND MOTOR THE SWITCH WAS BAD ONLY WORKED ON
THE RETRACT BUT NOT EXTEND PUT IN PO FOR NEW SWITCH

66540 1 THE SWITCH FOT THE REAR JACK WAS SMOKING WHEN USING IT
SCREW HOLDING SWITCH WAS TOUCHING THE CIRCUT BREAKER
PUT A SHORTER SCREW IN PLACE

66540 3 THE OUTDOOR GRILL IS MOUNTED FROM THE FACTORY IN A POSITION THAT
WILL NOT ALLOW THE LP HOSE TO REACH THE PORT.
GRILL HOSE WOULD NOT REACH PORT
LINE HAD 2 HOSE SUPPORTS REMOVED THE ONE THAT KEPT THE HOSE FROM
REACHING THE PORT TESTED THE CONNECTION TO MAKE SURE IT WOULD
REACH THE PORT

Part No Job# Description PARTS Qty Price Total

490960 2 LIPPERT STAB JACK 1.00 30.98 30.98

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.50 150.00 75.00
Z990 1 MISCELLANEOUS REPAIR 0.12 150.00 18.00
Z990 1 MISCELLANEOUS REPAIR 0.38 150.00 57.00

Claim : 66540

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      3    MISCELLANEOUS REPAIR      0.10     150.00     15.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       2    UPS-JACK SWITCH      1.00     11.76     11.76

```

```

Parts Total:      30.98
Labour Total:     165.00
Sublet Total:      0.00
Extras Total:     11.76

```

```

>>>> Claim Total:      207.74

```

Customer Signature: _____

Date: _____