



# Warranty Authorization Form

Date: 6/19/2026

Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

Pre-Auth #: 957646                      Unit: 573FM4436M1117889  
Series: Momentum                      Model: MT395MS-R-2021  
Notes: JPH 6-19-26 Thank you for that info.  
Status: Approved

### Dealer Information

1127 Greenway RV Sales & Service  
715-325-5170  
mail@greenwayrv.com

Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494

Requestor: iclaim services  
Return Fax #: (715) 325-5577  
Email: greenway@dealer-advisors.com

### Operation Line 1

*Flat Rate Code:* 620026 Floor Covering - Repair Linoleum Main Floor(per *Fault Code:* Damaged/Maintenance In. ft., including attachments)

*Serial #:*

*Model #:*

*Notes:*

*Problem:* There is a screw at the end of the bed that is pushing through the lino.

*Time Requested:* 1

*Cause:* Screw head popping up in the bedroom at the foot of the bed under the lino.

*Time Allowed:* 1

*Remedy:* Cut over screw, take screw out and small repair to lino.

*Sublet Repairs:* 0.00

*Status:* Approved