

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66552
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 52343 - DALE SALONEN
Address: 1333 33RD ST TELL CITY, IN

47586

Phone: 217-304-1528

Stock Number: 10972 - 2022 COUGAR HALF-TON 25RDS 4YDTCGM29NV504482

VIN: 4YDTCGM29NV504482 HIN:

SER#: 4YDTCGM29NV504482

Mileage: 0

Work Order Comp: 01 APR 22

Auth. No:

Dealer #: 1194

Warr. Date: 10 MAR 22

Work Order Date: 21 FEB 22

Inv #: 374788

WO # Job # Description JOB INFORMATION

66552 1 SLIDE ROOM LEAKING AND CEILING IS HANGING DOWN
metal piece that runs on top of the slide out behind the facia
isnt sealed and is causing water to leak through. took light off
slide out ceiling and water poured out of it. also fixing the
ceiling that is hanging down. ceiling isn't secured to the studs
and is cracked at the front.
ran slide out in. took corner trim piece off. took silicone and
ran all the way along the back of metal strip running along the
top. sealed corners. attached corner trim pulled trim down
around ceiling panel to see how to secure it. studs that are in
the ceiling are aluminum. took screws and secured panel. took
batten strips and covered both areas where we secured panel.
installed trim around panel. filled staple holes with putty.
cleaned up mess.

66552 3 TABLE BASE
SWAP TABLE BASE AND INSTALL D SEAL/BULB SEAL ON THE INSIDE OF
SLIDE OUT
PULLED DAMAGED BASE OFF TABLE TOP.. INSTALLED NEW BASE TO TABLE
TOP. SEALS WERE NOT IN THE BOX WHEN I OPENED IT. FOUND THE
CORRECT SEAL IN THE BACK ROOM. TOOK 12 FEET OF SEAL OUT OF BOX.
CRAIG IS TO PUT THE SEALS OWED FROM KEYSTONE IN THE BOX IN BACK
ROOM.

Part No Job# Description PARTS Qty Price Total

668568 1 Trim - Batten - 3. 1.00 3.35 3.35

Claim : 66552

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
302178        1   Seal - Co-Extruded          12.00      1.43      17.16
596844        3   Table - Leg/Bed Ba           1.00     84.34     84.34

```

```

*****
Lab Code Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990        1   MISCELLANEOUS REPAIR          0.00    150.00      0.00
Z990        1   MISCELLANEOUS REPAIR          0.00    150.00      0.00
Z990        1   MISCELLANEOUS REPAIR          0.50    150.00     75.00
Z990        1   MISCELLANEOUS REPAIR          0.00    150.00      0.00
Z990        1   MISCELLANEOUS REPAIR          0.00    150.00      0.00
Z990        1   MISCELLANEOUS REPAIR          0.00    150.00      0.00
Z990        1   MISCELLANEOUS REPAIR          0.00    150.00      0.00
Z990        3   MISCELLANEOUS REPAIR          0.20    150.00     30.00

```

```

*****
Excode      Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT          1   UPS-BATTEN                      1.00     37.02     37.02
FRT          1   UPS-SEAL & TABLE BASE         1.00     96.80     96.80
FRT          1   UPS-SEAL                       1.00     15.69     15.69

```

```

Parts Total:      104.85
Labour Total:     105.00
Sublet Total:       0.00
Extras Total:     149.51

```

>>>> Claim Total: 359.36

Customer Signature: _____

Date: _____