

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66650
MANUFACTURER'S CLAIM #:

Manufacturer: 1009 - FOREST RIVER INC.
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10891 - 2022 CHEROKEE WOLF PUP 16BHS 5ZT2CKEC3NY023732
VIN: 5ZT2CKEC3NY023732 HIN: SER#: 5ZT2CKEC3NY023732
Mileage: 0
Auth. No: Work Order Comp: 17 MAR 22
Warr. Date: Dealer #: 2070
Work Order Date: 03 MAR 22 Inv #: 374006

WO # Job # Description JOB INFORMATION

66650 1 BLACK TANK READS FULL BUT IS EMPTY
BLACK TANK WAS READING FULL WHEN EMPTY, DUE TO STAPLE OR NAIL
THROUGH WIRE DONE BY THE MANUFACTURE. YOU COULNDT EVEN MOVE OLD
WIRE IT WAS STUCK IN PLACE. BECAUSE OF THIS CAUSED A FALSE
READING TO READ FULL WHEN EMPTY
AFTER TRYING TO TRACE THE OLD WIRE FROM THE MODULE PANEL TO THE
TANK THAT RAN THROUHOUT THE CELLING. WE HAD TO REVOME
FRIDGE, MICROWAVE, AND CONVERTER AND HAD TO DRILL HOLES THROUGH
CABNIET COMPARTMENTS TO RUN THE NEW WIRE. WE RAN THE NEW WIRE
FROM THE CONTROL MODULE THROUGH THE CABNIETS AND DOWN THE FLOOR
WHERE THE FRIDGE IS AND DOWN AND OUT TO THE TANK. THIS FIXED THE
PROBLEM AND IS READING CORRECTLY. NEW WIRE FROM THE CONTROL
MODULE TO THE BLACK WATER TANK. THROUGH CABNIETS TO RUN THE NEW
WIRE. DUE TO THE NEW HOLES I HAD TO MAKE A NEW PANEL TO COVER
UP EXPOSED WIRE IN CABNIET.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOR CODE 0.20 150.00 30.00
Z990 1 MISC LABOR CODE 0.30 150.00 45.00
Z990 1 MISC LABOR CODE 2.00 150.00 300.00
Z990 1 MISC LABOR CODE 1.00 150.00 150.00

Parts Total: 0.00
Labour Total: 525.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 525.00

Customer Signature: _____

Date: _____

Claim : 66650

```
*****
Lab Code Job# Description      LABOUR      Hrs      Rate      Total
*****
```